

Procedures removed from ARINC output Cycle 1904

Type	Procedure	Transition	Reason
3S8_			Grants Pass, OR
	APCH		
	R13	CAMAS	published angle not coincident with calculated one.
	R13		published angle not coincident with calculated one.
CPZ3			Trenton / Mountain View, ON
	APCH		
	R06R	LEPAP	source inconsistency, not published in CAP/RCAP
	R06R	SEGEP	source inconsistency, not published in CAP/RCAP
	R06R	ZASER	source inconsistency, not published in CAP/RCAP
	R06R		source inconsistency, not published in CAP/RCAP
	R24L	ALIRA	source inconsistency, not published in CAP/RCAP
	R24L	GADEN	source inconsistency, not published in CAP/RCAP
	R24L	ODBAK	source inconsistency, not published in CAP/RCAP
	R24L		source inconsistency, not published in CAP/RCAP
DGLE			Tamale
	APCH		
	V05-Y	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Y		NOTAM B033/16 - THR 05 displaced
	V05-Z	R140J	NOTAM B033/16 - THR 05 displaced
	V05-Z	R320J	NOTAM B033/16 - THR 05 displaced
	V05-Z	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Z		NOTAM B033/16 - THR 05 displaced

Type	Procedure	Transition	Reason
EGVN			Brize Norton AB
	SID		
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible

FZMA			Bukavu / Kavumu
	APCH		
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06

FZNA			Goma Intl
	APCH		
	R17	ASMAT	Unsafe Source
	R17		Unsafe Source
	R35	NESOG	Unsafe Source
	R35	OLIKO	Unsafe Source
	R35	RIXAR	Unsafe Source
	R35		Unsafe Source

Type	Procedure	Transition	Reason
HLLT			Tripoli Intl
	SID		
	GARU1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	MIS1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	SARK1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	WLD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	STAR		
	GRT1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1E	RW27	VOR/DME TPI new coordinates, procedures not updated

Type	Procedure	Transition	Reason
HSSJ			Juba
APCH			
	R13	ALSAP	runway extended, procedure not updated
	R13	ALSOG	runway extended, procedure not updated
	R13	RALSA	runway extended, procedure not updated
	R13		runway extended, procedure not updated
KCLR			Calipatria / Cliff Hatfield Mem, CA
APCH			
	R08	BOREN	
	R08		
KEUG			Eugene / Mahlon Sweet Fld, OR
APCH			
	R34LZ	DRAIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SAGIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.

Type	Procedure	Transition	Reason
KLCK			Columbus / Rickenbacker Intl, OH
	APCH		
	R05L	GAILL	
	R05L	HIGID	
	R05L	TARTO	
	R05L		not trusted due to calc. angle of 3.16°
KTYS			Knoxville / Mc Ghee Tyson, TN
	APCH		
	I23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	I23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R	VXV	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
LGEL			Elefsis
	APCH		
	V36LA	R219N	Unclear source
	V36LA		Unclear source

Type	Procedure	Transition	Reason
LRSV			Suceava / Stefan cel Mare - Suceava
	APCH		
	R16	BUKOV	FAS DB not provided
	R16	HUMOR	FAS DB not provided
	R16	PASKA	FAS DB not provided
	R16	TOMUC	FAS DB not provided
	R16		FAS DB not provided
	R34	BUKOV	FAS DB not provided
	R34	HUMOR	FAS DB not provided
	R34	PASKA	FAS DB not provided
	R34	RIVKA	FAS DB not provided
	R34	TOMUC	FAS DB not provided
	R34		FAS DB not provided

SBGW			Guaratingueta, SP
	APCH		
	N02-A	GGT	procedure not compatibel with FMS requirements
	N02-A		procedure not compatibel with FMS requirements
	N20-B	GGT	procedure not compatibel with FMS requirements
	N20-B		procedure not compatibel with FMS requirements

Type	Procedure	Transition	Reason
SKCZ			Corozal / Las Brujas
	APCH		
	R03-X	CZ512	SUP C62/18 eff 11OCT18 ; conflict of Idents with existing RNAV Approach for that runwa
	R03-X	CZ514	SUP C62/18 eff 11OCT18 ; conflict of Idents with existing RNAV Approach for that runwa
	R03-X	CZ516	SUP C62/18 eff 11OCT18 ; conflict of Idents with existing RNAV Approach for that runwa
	R03-X	CZ590	SUP C62/18 eff 11OCT18 ; conflict of Idents with existing RNAV Approach for that runwa
	R03-X		SUP C62/18 eff 11OCT18 ; conflict of Idents with existing RNAV Approach for that runwa
SKQU			Mariquita / Jose Celestino Mutis
	APCH		
	V01-A	MQU	circling apch not leading to RWY, final track offset by more than 15 DEG.
	V01-A		circling apch not leading to RWY, final track offset by more than 15 DEG.
TUPJ			Roadtown / Terrance B. Lettsome Intl.
	APCH		
	N07-B	STT	vertical angle cannot be determined
	N07-B		vertical angle cannot be determined
VYPN			Pathein
	APCH		
	V06	PTN	repositioning of PTN VORDME, AMDT 1/2016
	V06		repositioning of PTN VORDME, AMDT 1/2016
	V24	PTN	repositioning of PTN VORDME, AMDT 1/2016
	V24		repositioning of PTN VORDME, AMDT 1/2016
WAPP			Ambon / Pattimura
	APCH		
	R22		no RF Center Fix published