

## Procedures removed from ARINC output Cycle 1906

Type	Procedure	Transition	Reason
<b>3S8_</b>			Grants Pass, OR
	APCH		
	R13	CAMAS	published angle not coincident with calculated one.
	R13		published angle not coincident with calculated one.
<b>CPZ3</b>			Trenton / Mountain View, ON
	APCH		
	R06R	LEPAP	source inconsistency, not published in CAP/RCAP
	R06R	SEGEP	source inconsistency, not published in CAP/RCAP
	R06R	ZASER	source inconsistency, not published in CAP/RCAP
	R06R		source inconsistency, not published in CAP/RCAP
	R24L	ALIRA	source inconsistency, not published in CAP/RCAP
	R24L	GADEN	source inconsistency, not published in CAP/RCAP
	R24L	ODBAK	source inconsistency, not published in CAP/RCAP
	R24L		source inconsistency, not published in CAP/RCAP
<b>DGLE</b>			Tamale
	APCH		
	V05-Y	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Y		NOTAM B033/16 - THR 05 displaced
	V05-Z	R140J	NOTAM B033/16 - THR 05 displaced
	V05-Z	R320J	NOTAM B033/16 - THR 05 displaced
	V05-Z	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Z		NOTAM B033/16 - THR 05 displaced

Type	Procedure	Transition	Reason
<b>EGVN</b>	Brize Norton AB		
	SID		
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible
<b>FZMA</b>	Bukavu / Kavumu		
	APCH		
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	Incorrect Source: AIRAC AIP SUP S3006/06	
<b>FZNA</b>	Goma Intl		
	APCH		
	R17	ASMAT	Unsafe Source
	R17		Unsafe Source
	R35	NESOG	Unsafe Source
	R35	OLIKO	Unsafe Source
	R35	RIXAR	Unsafe Source
	R35	Unsafe Source	

Type	Procedure	Transition	Reason
<b>HLLT</b>			Tripoli Intl
	SID		
	GARU1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	MIS1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	SARK1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	WLD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	STAR		
	GRT1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1E	RW27	VOR/DME TPI new coordinates, procedures not updated

Type	Procedure	Transition	Reason
<b>HSSJ</b>			Juba
APCH			
	R13	ALSAP	runway extended, procedure not updated
	R13	ALSOG	runway extended, procedure not updated
	R13	RALSA	runway extended, procedure not updated
	R13		runway extended, procedure not updated
<b>KCLR</b>			Calipatria / Cliff Hatfield Mem, CA
APCH			
	R08	BOREN	
	R08		
<b>KEUG</b>			Eugene / Mahlon Sweet Fld, OR
APCH			
	R34LZ	DRAIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SAGIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.

Type	Procedure	Transition	Reason
<b>KLCK</b>			Columbus / Rickenbacker Intl, OH
	APCH		
	R05L	GAILL	
	R05L	HIGID	
	R05L	TARTO	
	R05L		not trusted due to calc. angle of 3.16°
<b>KTYS</b>			Knoxville / Mc Ghee Tyson, TN
	APCH		
	I23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	I23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R	VXV	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
<b>LGEL</b>			Elefsis
	APCH		
	V36LA	R219N	Unclear source
	V36LA		Unclear source

Type	Procedure	Transition	Reason
<b>LRSV</b>			Suceava / Stefan cel Mare - Suceava
	APCH		
	R16	BUKOV	FAS DB not provided
	R16	HUMOR	FAS DB not provided
	R16	PASKA	FAS DB not provided
	R16	TOMUC	FAS DB not provided
	R16		FAS DB not provided
	R34	BUKOV	FAS DB not provided
	R34	HUMOR	FAS DB not provided
	R34	PASKA	FAS DB not provided
	R34	RIVKA	FAS DB not provided
	R34	TOMUC	FAS DB not provided
	R34		FAS DB not provided

<b>SBGW</b>			Guaratingueta, SP
	APCH		
	N02-A	GGT	procedure not compatibel with FMS requirements
	N02-A		procedure not compatibel with FMS requirements
	N20-B	GGT	procedure not compatibel with FMS requirements
	N20-B		procedure not compatibel with FMS requirements

<b>SKQU</b>			Mariquita / Jose Celestino Mutis
	APCH		
	V01-A	MQU	circling apch not leading to RWY, final track offset by more than 15 DEG.
	V01-A		circling apch not leading to RWY, final track offset by more than 15 DEG.

	Type	Procedure	Transition	Reason
<b>VYPN</b>				Pathein
		APCH		
		V06	PTN	repositioning of PTN VORDME, AMDT 1/2016
		V06		repositioning of PTN VORDME, AMDT 1/2016
		V24	PTN	repositioning of PTN VORDME, AMDT 1/2016
	V24		repositioning of PTN VORDME, AMDT 1/2016	
<b>WAPP</b>				Ambon / Pattimura
		APCH		
	R22			no RF Center Fix published