

## Exclusion List for GE NavDBs in Cycle 2009

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 2009. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
<b>012</b>		Brazil Clay County
	APCH	
	R27	5
	V09	5
<b>12N</b>		Andover/Aeroflex-Andover
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>CYYT</b>		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
<b>EBBE</b>		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

\*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

**EBBL**

Kleine Brogel

SID		
	BL05A	22
	BL05B	22
	BL05D	22

**EBFS**

Florennes

SID		
	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

**EGHC**

Penzance/Lands End

APCH		
	R07	5
	R16	5
	R25	5
	R34	5

**EGHE**

St Mary's/Scilly Isles

APCH		
	N27	5
	N32	5

**EGJA**

St Annes/Alderney

APCH		
	N08	5
	N26	5

**EGYD**

Cranwell

SID		
	SID1B	5

**EHEH**

Eindhoven

SID		
	EH5	22

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>ENBL</b>		Forde/Bringeland
	APCH	
	J07	1
	J25	1
<b>ENBN</b>		Bronnoysund/Bronnoy
	APCH	
	J03	1
<b>ENBS</b>		Batsfjord
	APCH	
	J03	1
	J21	1
<b>ENBV</b>		Berlevag
	APCH	
	J06	1
	J24	1
<b>ENHF</b>		Hammerfest
	APCH	
	J04	1
	J22	1
<b>ENHK</b>		Hasvik
	APCH	
	J11	1
	J29	1
<b>ENLK</b>		Leknes
	APCH	
	J20	1
<b>ENMH</b>		Mehamn
	APCH	
	J17	1
	J35	1
<b>ENMS</b>		Mosjoen/Kjaerstad
	APCH	
	J34	1
<b>ENNM</b>		Namsos
	APCH	
	J07	1
	J25	1

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>ENRM</b>		Rorvik/Ryum
	APCH	
	J04	1
	J22	1
<b>ENRS</b>		Rost
	APCH	
	J02	1
	J20	1
<b>ENSH</b>		Svolvaer/Helle
	APCH	
	J01	1
<b>ENSK</b>		Stokmarknes/Skagen
	APCH	
	J09	1
<b>ENSS</b>		Vardo/Svartnes
	APCH	
	J15	1
	J33	1
<b>ENST</b>		Stokka/Sandnessjoen
	APCH	
	J02	1
	J20	1
<b>ENVD</b>		Vadso
	APCH	
	J07	1
	J25	1
<b>EPPR</b>		Pruszcz Gdanski
	APCH	
	N27-X	5
	N27-Y	5
	N27-Z	5
<b>ETHB</b>		Buckeburg
	SID	
	HB11	5
	HB12	5
	HB13	5
	HB31	5
	HB32	5
HB33	5	

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ETNG</b>			Geilenkirchen
		SID	
		NG13	11
		NG227	22
		NG33	22
<b>ETSL</b>			Lechfeld
		SID	
		SL303	22
		SL403	22
		SL921	22
<b>EVLA</b>			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
<b>GVSV</b>			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22
<b>KENV</b>			Wendover
		APCH	
		R08	5
<b>KHTO</b>			East Hampton
		APCH	
		R10-X	5
<b>KMTN</b>			Baltimore/Martin State
		APCH	
		T15	31
		V15	31
<b>KVKX</b>			Friendly/Potomac Airfield
		APCH	
		R06	5
<b>LFBD</b>			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LHKE</b>			Kecskemet
		APCH	
		N12	5
		N30	5
<b>LHPA</b>			Papa AB
		APCH	
		N16	5
<b>LIMS</b>			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
<b>MRLB</b>			Liberia/Daniel Oduber Quiros I
		APCH	
		V07	2
<b>MSSS</b>			San Salvador/Ilopango Intl
		APCH	
		V15	5
<b>N07</b>			Lincoln Park
		APCH	
		R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
<b>N85</b>			Pittstown/Alexandria
		APCH	
		D08	5
<b>NTAA</b>			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
<b>NTTE</b>			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>NTTG</b>			Rangiroa
	APCH	V27-X	5
<b>NZTK</b>			Takaka
	APCH	R18-Y	5
<b>NZWB</b>			Woodbourne
	STAR	NORTHV	27
		WESTV	27
<b>OEGT</b>			Guriat Domestic
	APCH	V28	2
<b>OERR</b>			Arar Domestic
	APCH	V10	2
<b>PARS</b>			Russian Mission
	APCH	R36	5
<b>RKSM</b>			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SBFZ</b>			Fortaleza/Pinto Martins Intl
	APCH	V31	2
<b>SBSN</b>			Santarem/Maestro Wilson Fonsec
	APCH	V10	2
		V28	2
<b>SKUL</b>			Tulua/Heriberto Gil Martinez
	APCH	V02	5
<b>UHPK</b>			Ust-Kamchatsk
	STAR	DOMUD2	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>UIUU</b>			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	
<b>UKHK</b>			Kremenchuk/Velyka Kokhivka Na
		APCH	
		N36	5
<b>URRT</b>			Taganrog/Yuzhny
		APCH	
		N10-X	5
		N28-X	5
<b>UWGG</b>			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
<b>WAJI</b>			Sarmi/Orai
		APCH	
		R13	5
<b>WAKE</b>			Bade
		APCH	
		R02	5
		R20	5
<b>WASA</b>			Ayawasi
		APCH	
		R09	5
		R27	5
<b>WASI</b>			Inanwatan
		APCH	
		R08	5
		R26	5

\*See Reason Code table on page R1



	Type	Procedure	Reason*
<b>WAUM</b>			Merdei/Jahabra
	APCH		
		R27	5
<b>WAYK</b>			Kokonao
	APCH		
		H13	5
<b>WIRR</b>			Tangerang/Budiarto
	APCH		
		V30	5
<b>ZGSD</b>			Zhuhai/Jinwan
	STAR		
		F02A	22
<b>ZYTX</b>			Shenyang/Taoxian
	STAR		
		ANS02A	22
		TOS02A	22

\*See Reason Code table on page R1

## Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55