

Procedures removed from ARINC output Cycle 2013

Type	Procedure	Transition	Reason
CPZ3			Trenton / Mountain View, ON
	APCH		
	R06R	LEPAP	source inconsistency, not published in CAP/RCAP
	R06R	SEGEP	source inconsistency, not published in CAP/RCAP
	R06R	ZASER	source inconsistency, not published in CAP/RCAP
	R06R		source inconsistency, not published in CAP/RCAP
	R24L	ALIRA	source inconsistency, not published in CAP/RCAP
	R24L	GADEN	source inconsistency, not published in CAP/RCAP
	R24L	ODBAK	source inconsistency, not published in CAP/RCAP
	R24L		source inconsistency, not published in CAP/RCAP
DTTZ			Tozeur / Nefta
	APCH		
	V27-X	TON	Notam DT A2253/20
	V27-X		Notam DT A2253/20
EGVN			Brize Norton AB
	SID		
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible

Type	Procedure	Transition	Reason
FMMS			Sainte Marie
	APCH		
	N01	SM	Notam A1096/19
	N01		Notam A1096/19
	N19	SM	Notam A1096/19
	N19		Notam A1096/19

FZMA			Bukavu / Kavumu
	APCH		
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06

FZNA			Goma Intl
	APCH		
	R35	NESOG	Unsafe Source
	R35	OLIKO	Unsafe Source
	R35	RIXAR	Unsafe Source
	R35		Unsafe Source

Type	Procedure	Transition	Reason
HLLT			Tripoli Intl
	SID		
	GARU1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	MIS1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	SARK1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	WLD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	STAR		
	GRT1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1E	RW27	VOR/DME TPI new coordinates, procedures not updated

Type	Procedure	Transition	Reason
KCLR			Calipatria / Cliff Hatfield Mem, CA
	APCH		
	R08	BOREN	
	R08		
KEUG			Eugene / Mahlon Sweet Fld, OR
	APCH		
	R34LZ	DRAIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34LZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SAGIN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	SHEDD	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VAUGN	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ	VIDAS	FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
	R34RZ		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
KLCK			Columbus / Rickenbacker Intl, OH
	APCH		
	R05L	GAILL	
	R05L	HIGID	
	R05L	TARTO	
	R05L		not trusted due to calc. angle of 3.16°

Type	Procedure	Transition	Reason
KTYS			Knoxville / Mc Ghee Tyson, TN
	APCH		
	I23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	I23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R	VXV	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15

Type	Procedure	Transition	Reason
LRSV			Suceava / Stefan cel Mare - Suceava
	APCH		
	R16	BUKOV	FAS DB not provided
	R16	HUMOR	FAS DB not provided
	R16	PASKA	FAS DB not provided
	R16	TOMUC	FAS DB not provided
	R16		FAS DB not provided
	R34	BUKOV	FAS DB not provided
	R34	HUMOR	FAS DB not provided
	R34	PASKA	FAS DB not provided
	R34	RIVKA	FAS DB not provided
	R34	TOMUC	FAS DB not provided
	R34		FAS DB not provided

LSMD			Dubendorf
	APCH		
	H29-X	MD519	coding table not up to date
	H29-X		coding table not up to date
	H29-Y	MD514	coding table not up to date
	H29-Y	MD516	coding table not up to date
	H29-Y		coding table not up to date

Type	Procedure	Transition	Reason
NZAA			Auckland
APCH			
I05R	LENGU		AMDT 06/20
I05R	R142M		AMDT 06/20
I05R	R332M		AMDT 06/20
I05R			AMDT 06/20
I05RE	LENGU		AMDT 06/20
I05RE	R142M		AMDT 06/20
I05RE	R332M		AMDT 06/20
I05RE			AMDT 06/20
I23L	R165M		AMDT 06/20
I23L	R305M		AMDT 06/20
I23L			AMDT 06/20
I23LW	R165M		AMDT 06/20
I23LW	R305M		AMDT 06/20
I23LW			AMDT 06/20
L05R	LENGU		AMDT 06/20
L05R	R142M		AMDT 06/20
L05R	R332M		AMDT 06/20
L05R			AMDT 06/20
L05RE	LENGU		AMDT 06/20

Type	Procedure	Transition	Reason
	L05RE	R142M	AMDT 06/20
	L05RE	R332M	AMDT 06/20
	L05RE		AMDT 06/20
	L23L	EMRAG	AMDT 06/20
	L23L	R165M	AMDT 06/20
	L23L	R305M	AMDT 06/20
	L23L		AMDT 06/20
	L23LE	EMRAG	AMDT 06/20
	L23LE	R165M	AMDT 06/20
	L23LE	R305M	AMDT 06/20
	L23LE		AMDT 06/20
	L23LW	EMRAG	AMDT 06/20
	L23LW	R165M	AMDT 06/20
	L23LW	R305M	AMDT 06/20
	L23LW		AMDT 06/20
	R05RE	LENGU	AMDT 06/20
	R05RE		AMDT 06/20
	R05RX		AMDT 06/20
	R05RY		AMDT 06/20

Type	Procedure	Transition	Reason
	R05RZ	LENGU	AMDT 06/20
	R05RZ		AMDT 06/20
	R23LZ	EMRAG	AMDT 06/20
	R23LZ		AMDT 06/20
	V05R	LENGU	AMDT 06/20
	V05R	R142M	AMDT 06/20
	V05R	R332M	AMDT 06/20
	V05R		AMDT 06/20
	V05RE	LENGU	AMDT 06/20
	V05RE	R142M	AMDT 06/20
	V05RE	R332M	AMDT 06/20
	V05RE		AMDT 06/20
	V23L	EMRAG	AMDT 06/20
	V23L	R165M	AMDT 06/20
	V23L	R305M	AMDT 06/20
	V23L		AMDT 06/20
	V23LE	EMRAG	AMDT 06/20
	V23LE	R165M	AMDT 06/20
	V23LE	R305M	AMDT 06/20

Type	Procedure	Transition	Reason
	V23LE		AMDT 06/20

RJSF

Fukushima

APCH			
	I01-X	FKE	SUP 183/20
	I01-X		SUP 183/20
	L01-X	FKE	SUP 183/20
	L01-X		SUP 183/20

SBGW

Guaratingueta, SP

APCH			
	N02-A	GGT	procedure not compatibel with FMS requirements
	N02-A		procedure not compatibel with FMS requirements
	N20-B	GGT	procedure not compatibel with FMS requirements
	N20-B		procedure not compatibel with FMS requirements

SKQU

Mariquita / Jose Celestino Mutis

APCH			
	V01-A	MQU	circling apch not leading to RWY, final track offset by more than 15 DEG.
	V01-A		circling apch not leading to RWY, final track offset by more than 15 DEG.

Type	Procedure	Transition	Reason
UHMD			Provideniya Bay
	SID		
	BAMRI	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	BAMRI	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIMRA	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIMRA	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LALOK	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LALOK	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.

Type	Procedure	Transition	Reason
STAR			
	ABINA	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	ABINA	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	INGUS	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	INGUS	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LIKOK	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LIKOK	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.

Type	Procedure	Transition	Reason
UUBW			Ramenskoye
	STAR		
	BILR1T	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	ESOL1T	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	IDPI1F	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	NIGL1X	RW12	WPT BW152 coords missing/BW146 incorrect (pending CLAR)
	RAMU1F	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	REKP1J	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	TENR1T	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	UDAP1F	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	URAG1T	RW12	WPT BW152 coords missing/BW146 incorrect (pending CLAR)
	URAG1U	RW30	WPT BW152 coords missing/BW146 incorrect (pending CLAR)
	URAG1V	RW12	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	APCH		
	H12	BW107	waypoints seem to be wrong
	H12		waypoints seem to be wrong
	H12-X	BW146	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	H12-X		coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	N12	BW107	coords for BW146/BW152 missing or considered incorrect (pending CLAR)
	V12	BW107	coords for BW146/BW152 missing or considered incorrect (pending CLAR)

Type	Procedure	Transition	Reason
WAPP			Ambon / Pattimura
	APCH		
	R22		no RF Center Fix published

Type	Procedure	Transition	Reason
WIJJ			Jambi / Sultan Thaha
	APCH		
	I31	MUARO	AIRAC AMDT 96/20, Notam C1030/20
	I31		AIRAC AMDT 96/20, Notam C1030/20
	L31	MUARO	AIRAC AMDT 96/20, Notam C1030/20
	L31		AIRAC AMDT 96/20, Notam C1030/20
	N31-Y	NX	AIRAC AMDT 96/20, Notam C1030/20
	N31-Y		AIRAC AMDT 96/20, Notam C1030/20
	N31-Z	NX	AIRAC AMDT 96/20, Notam C1030/20
	N31-Z		AIRAC AMDT 96/20, Notam C1030/20