
Flight Safety Alert

AIRAC 1806 – Issue 5

SUP OP S-07/18 effective 15th March 2018

OPIS Islamabad

SID BOBAM 1M

- Turn direction to waypoint IS412 is missing. Turn direction should read **LEFT**.

Navdata will be updated effective AIRAC cycle 1807.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
16th May 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com