

---

## Navigation Database Addendum

### **AIRAC 1902 – Issue 17**

### **OTBH AI Udeid AB**

---

#### **APCH ILS RWY 34L, LOC RWY 34L**

Localizer frequency ITCE RWY 34L should read 111.10 MHz instead of 110.95 MHz.

Navdata will be updated effective AIRAC cycle 1903.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
29<sup>th</sup> January 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)