

Procedures removed from ARINC output Cycle 2611

Type	Procedure	Transition	Reason
AYKV	Kavieng		
	APCH		
	R30	YKVED	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30	YKVEE	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30	YKVEG	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30		Notam AY A1069/22 THR RWY 30 coordinates changed
DAUB	Biskra / Mohamed Khider		
	APCH		
	I31	BIS	RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
	I31		RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
DNIB	Ibadan / Samuel Ladoke Akintola Airport		
	APCH		
	R04	DEGOV	The RWY has been extended by 600m, but the procedure has not yet been adjusted.
	R04	IVLOL	The RWY has been extended by 600m, but the procedure has not yet been adjusted.
	R04	KOBVO	The RWY has been extended by 600m, but the procedure has not yet been adjusted.
	R04		The RWY has been extended by 600m, but the procedure has not yet been adjusted.
DNKS	Kashimbila		
	APCH		
	H13	IVGIR	ALT published on final not correct - DN AIRAC AMDT 03/2026
	H13	XUMSO	ALT published on final not correct - DN AIRAC AMDT 03/2026
	H13		ALT published on final not correct - DN AIRAC AMDT 03/2026
	H31	EBTEM	ALT published on final not correct - DN AIRAC AMDT 03/2026
	H31		ALT published on final not correct - DN AIRAC AMDT 03/2026

	Type	Procedure	Transition	Reason
DNMN				Minna
		APCH		
		I05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		I05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
EGVN				Brize Norton AB
		SID		
		ALPHA	RW07	Different Endfixes not possible
		ALPHA	RW25	Different Endfixes not possible
		BRAVO	RW07	Different Endfixes not possible
		BRAVO	RW25	Different Endfixes not possible
FMMS				Sainte Marie
		APCH		
		N01	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N01		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD

Type	Procedure	Transition	Reason
FNLU Luanda / 4th of February			
APCH			
	I23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
FZKA Bunia			
APCH			
	R09	PESUX	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09	UXIMO	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09	VEBID	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09		NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27	ABGAX	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27	EKLIT	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27	IDMED	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27		NOTAM FZ B0064/2026 updated the RWY coordinates.
FZMA Bukavu / Kavumu			
APCH			
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06

	Type	Procedure	Transition	Reason
HKLK				Lokichoggio
	APCH			
		H27	EPSUT	HK Notam B0002/21
		H27		HK Notam B0002/21
HLLT				Tripoli Intl
	STAR			
		IZD1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
		SINA1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
KLCK				Columbus / Rickenbacker Intl, OH
	APCH			
		R05L	GAILL	
		R05L	HIGID	
		R05L	TARTO	
		R05L		not trusted due to calc. angle of 3.16°
OAKB				Kabul Intl
	SID			
		TAPIS2	RW11	RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)
	APCH			
		R29		RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)

	Type	Procedure	Transition	Reason
RKJB				Muan Intl
	APCH			
	H19	AYEON		RK SUP 43/26 (THR19 displ 300m) end-dated to 03SEP26. AIP charts still published with displ THR coor
	H19	DOWAN		RK SUP 43/26 (THR19 displ 300m) end-dated to 03SEP26. AIP charts still published with displ THR coor
	H19			RK SUP 43/26 (THR19 displ 300m) end-dated to 03SEP26. AIP charts still published with displ THR coor
	V19	DOVRA		RK SUP 43/26 (THR19 displ 300m) end-dated to 03SEP26. AIP charts still published with displ THR coor
	V19	GUPLA		RK SUP 43/26 (THR19 displ 300m) end-dated to 03SEP26. AIP charts still published with displ THR coor
SVRS				El Gran Roque Natl
	APCH			
	H25	ANLEG		SV AIRAC SUP C 03/A03 2026
	H25	TOROP		SV AIRAC SUP C 03/A03 2026
	H25			SV AIRAC SUP C 03/A03 2026

	Type	Procedure	Transition	Reason
UERP				Poliarny
	SID			
		ABNI1F	RW36	NTM UE C3683/25 (proc not to be used)
		BAGO1F	RW36	NTM UE C3683/25 (proc not to be used)
		BALU1F	RW36	NTM UE C3683/25 (proc not to be used)
		DEDO1F	RW36	NTM UE C3683/25 (proc not to be used)
		FADR1F	RW36	NTM UE C3683/25 (proc not to be used)
		GILA1F	RW36	NTM UE C3683/25 (proc not to be used)
		INDI1F	RW36	NTM UE C3683/25 (proc not to be used)
		NERD1F	RW36	NTM UE C3683/25 (proc not to be used)
		OGON1F	RW36	NTM UE C3683/25 (proc not to be used)
		PELI1F	RW36	NTM UE C3683/25 (proc not to be used)
		PIRO1F	RW36	NTM UE C3683/25 (proc not to be used)
		RUSE1F	RW36	NTM UE C3683/25 (proc not to be used)
		SUGI1F	RW36	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
STAR			
	ABNI1L	RW18	NTM UE C3683/25 (proc not to be used)
	ABNI1L	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW18	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW18	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW18	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW18	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW18	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW18	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW18	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW18	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1L	RW18	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
	PELI1L	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW18	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW18	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW18	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW36	NTM UE C3683/25 (proc not to be used)
APCH			
	J18	RP003	NTM UE C3298/24
	J18	RP004	NTM UE C3298/24
	J18		NTM UE C3298/24
	V18	PLR	NTM UE C3683/25 (proc not to be used)
	V18		NTM UE C3683/25 (proc not to be used)
	V36	PLR	NTM UE C3683/25 (proc not to be used)
	V36		NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
UUOO	Voronezh / Chertovitskoye		
	APCH		
	J30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	J30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
VLVT	Vientiane / Wattay Intl		
	SID		
	BIK1C	RW31	Lao AIRAC SUP A04/25 - WEF 30 OCT 2025. Mismatch between graphical depiction and procedure text