Exclusion List for HWL NavDBs in Cycle 2612

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2612. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

	Type	Procedure	Reason*	
07FA				Key Largo/Ocean Reef Club
	APCH			
		R05-P	40	
		R23-P	40	
0ID2				May/Flying Joseph Ranch
	APCH			
		R11-M	40	
	SID			
		YOYYU1	40	
		ZAROD1	40	
10X				Uvalde/Ox Ranch
	APCH			
		R17-M	40	
		R35-M	40	
17XS				Dublin/Quahadi Ranch
	APCH			
		R01	40	
		R19	40	
64OG				Mitchell/Antone Ranch
	APCH			
		R25-M	40	
	SID			
		RIFTE1	40	
7FL6				Daytona Beach/Spruce Creek
	APCH			
		R06	40	
CAJ9				Fort Ware
	APCH			
		R11-Y	40	
		R11-Z	40	
		R29-Y	40	
		R29-Z	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CAM2				Misaw Lake
	APCH			
		R01	40	
		R19	40	
CBH2				Helmet
	APCH			
		R12	40	
		R30	40	
CBN9				Tsay Keh
	APCH			
		R31	40	
CBQ7				Kemess Creek
	APCH			
		R11-Y	40	
		R11-Z	40	
		R29	40	
	SID			
		AVRED1	40	
CBW4				Bob Quinn Lake
	APCH			
		R15-Y	40	
		R15-Z	40	
CBX7				Tumbler Ridge
	APCH			
		R20	40	
	SID			
		KISKK6	40	
CCB2				Seabee Mine
	APCH			
		R05	40	
		R23	40	
CCE3				Juniper
	APCH			
		R02	40	
		R20	40	
CCJ3				Boston Brook
	APCH			
		R02	40	
		R20	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CCL3				Christina Lake
	APCH			
		R08	40	
		R26	40	
CCL6				Chilko Lake/Wilderness Lodge
	APCH			
		R16	40	
CCR3				Florenceville
	APCH			
		R18	40	
		R36	40	
CCS4				Chipman
	APCH			
		R09	40	
		R27	40	
CDA5				St Andrews/Codroy Valley
	SID			
		ODP18	40	
		ODP36	40	
CDJ4				Clearwater
	APCH			
		R14	40	
		R32	40	
CDJ5				Strathmore/D.J. Murray
	APCH			
		R16	40	
		R34	40	
CDP3				Utik Lake/Dennis G Punches Fie
	APCH			
		R09	40	
		R27	40	
CDT5				Bouctouche
	APCH			
		R09	40	
		R27	40	
CDU6				Doaktown
	APCH			
		R11	40	
		R29	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CDV2				Downs Gulch
	APCH			
		R05	40	
		R23	40	
CEC4				Hinton/Jasper-Hinton
	APCH			
		R02	40	
CEE5				Wabasca
	APCH			
		R07	40	
		R25	40	
CEG8				North Seal River
	APCH			
		R03	40	
		R21	40	
CEP3				Barrhead
	APCH			
		R07	40	
		R25	40	
CET9				Jean Marie River
	APCH			
		R11	40	
		R29	40	
CEU9				Sambaa K'e
	APCH			
		R22-Y	40	
CFH4				Fox Harbour
	APCH			
		R15	40	
		R33	40	
CFN6				Primrose
	APCH			
		R14	40	
	SID			
		VETPA2	40	
CFQ6				Pelly Crossing
	APCH			
		R08	40	
		R26	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CFT8				Pelican
	APCH			
		R07	40	
		R25	40	
CHB3				Hope Bay
	APCH			
		R01-Y	40	
		R01-Z	40	
		R19	40	
CJA3				Morden Rgnl
	APCH			
		R10	40	
		R28	40	
CJB3				Steinbach
	APCH			
		R15	40	
CJK3				Beauval
	APCH			
		R10	40	
		R28	40	
CJL4				La Loche
	APCH			
		R12	40	
		R30	40	
CJL8				Kasba Lake
	APCH			
		R02	40	
		R20	40	
CJP9				Charlot River
	APCH			
		R05-Y	40	
		R23	40	
CJQ3				Carlyle
	APCH			
		R11	40	
		R29	40	
CJQ4				Maple Creek
	APCH			
		R06	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CJW4				Pelican Narrows
	APCH			
		R01	40	
		R19	40	
CJY4				Sandy Bay
	APCH			
		R05	40	
		R23	40	
CKB2				Patuanak
	APCH			
		R14	40	
		R32	40	
CKD5				Kipling
	APCH			
		R10	40	
CKM8				Opapimiskan Lake
	APCH			
		R12	40	
		R30	40	
CKZ3				Elk Island
	APCH			
		R06	40	
		R24	40	
CKZ7				Winkler
	APCH			
		R09	40	
		R27	40	
CMB2				Meadowbank
	APCH			
		R12-Y	40	
		R12-Z	40	
		R30-Y	40	
		R30-Z	40	
CMB7				Maxville/Bourdon Farm
	APCH			
		R16	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CNL9				Nueltin Lake
	APCH			
		R02	40	
		R20	40	
CNV8				Edenvale
	APCH			
		R13	40	
CRL4				Kirby Lake
	APCH			
		R08	40	
		R26	40	
	SID			
		KIRBY7	40	
CRW4				Arctic Watch Lodge
	APCH			
		R01	40	
		R19	40	
	SID			
		ANEGU1	40	
CSR3				Victoriaville Andre-Fortin
	APCH			
		R24	40	
CSR8				La Sarre
	APCH			
		R36	40	
CSZ4				St-Frederic
	APCH			
		R23	40	
CTH7				Riviere-Aux-Saumons
	APCH			
		R10	40	
		R28	40	
CVB2				Voisey's Bay
	APCH			
		R10	40	
		R28	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CYAU				Liverpool/South Shore Rgnl
	APCH			
		R07	40	
		R25	40	
	SID			
		ODP07	40	
		ODP25	40	
CYBG				Bagotville
	APCH			
		I11-X	40	
		I29-X	40	
		L11-X	40	
		L29-X	40	
		R11-X	40	
		R29-X	40	
CYCZ				Fairmont Hot Springs
	SID			
		TEVED1	40	
CYDL				Dease Lake
	APCH			
		R03-X	40	
		R03-Y	40	
		R03-Z	40	
		R21-X	40	
		R21-Y	40	
		R21-Z	40	
	SID			
		OMRUN2	40	
		TIBID1	40	
CYDM				Ross River
	APCH			
		R09	40	
CYIB				Atikokan Muni
	APCH			
		R04	40	
		R22	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CYKA				Kamloops
	APCH			
		I09	40	
		L27-Y	40	
		R09-Y	40	
		R09-Z	40	
		R27-Y	40	
		R27-Z	40	
CYLW				Kelowna
	APCH			
		I16-Y	40	
		I16-Z	40	
		R16-V	40	
		R16-X	40	
CYMW				Maniwaki
	APCH			
		R21	40	
CYNN				Nejanilini Lake
	APCH			
		R18	40	
		R36	40	
CYPZ				Burns Lake
	APCH			
		R11-Y	40	
		R11-Z	40	
		R29-Y	40	
		R29-Z	40	
	SID			
		CYPZ6	40	
		ODPV	40	
CYTB				Tillsonburg
	APCH			
		R26	40	
CYTZ				Toronto/B Bishop Toronto City
	APCH			
		R08-W	40	
		R08-X	40	
		R26-X	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
CYZG				Salluit
	APCH			
		R03-X	40	
CZAM				Salmon Arm
	APCH			
		R14	40	
		R32	40	
CZML				South Cariboo/108 Mile
	APCH			
		R15	40	
		R33	40	
CZPO				Pinehouse Lake
	APCH			
		R16	40	
		R34	40	
EBBE				Beauvechain
	SID			
		BE22A	22	
		BE22B	22	
EBFS				Florennes
	SID			
		FS08A	22	
		FS08B	22	
		FS08C	22	
		FS08D	22	
		FS08E	22	
		FS26A	22	
		FS26B	22	
		FS26C	22	
		FS26D	22	
		FS26E	22	
EGNH				Blackpool
	APCH			
		N10	3	
EGNV				Teesside International
	APCH			
		N23	3	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
EGPO				Stornoway
	APCH			
		L36	3	
		N18	3	
		N36	3	
EGTE				Exeter
	APCH			
		N26	3	
EHEH				Eindhoven
	SID			
		EH5	22	
ENBL				Forde/Bringeland
	APCH			
		J07	1	
		J25	1	
ENBN				Bronnoysund/Bronnoy
	APCH			
		J03	1	
ENBS				Batsfjord
	APCH			
		J03	1	
		J21	1	
ENBV				Berlevag
	APCH			
		J06	1	
		J24	1	
ENHF				Hammerfest
	APCH			
		J04-Z	1	
		J22-Z	1	
ENHK				Hasvik
	APCH			
		J11	1	
		J29	1	
ENLK				Leknes
	APCH			
		J20	1	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
ENMH				Mehamn
	APCH			
		J17	1	
		J35	1	
ENNM				Namsos
	APCH			
		J07	1	
		J25	1	
ENRM				Rorvik/Ryum
	APCH			
		J04	1	
		J22	1	
ENRS				Rost
	APCH			
		J02	1	
		J20	1	
ENSH				Svolvaer/Helle
	APCH			
		J36	1	
ENSS				Vardo/Svartnes
	APCH			
		J15	1	
		J33	1	
ENST				Stokka/Sandnessjoen
	APCH			
		J02	1	
		J20	1	
ENVD				Vadso
	APCH			
		J07	1	
		J25	1	
ETNG				Geilenkirchen
	SID			
		NG227	22	
FA54				Placida/Coral Creek
	APCH			
		R05	40	
		R23	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
KASE				Aspen-Pitkin County/Sardy Fld
	APCH			
		L15	40	
KDLH				Duluth Intl
	APCH			
		T09	19	
		T09-Y	19	
		T09-Z	19	
KDYS				Abilene/Dyess AFB
	APCH			
		T16-W	19	
		T16-X	19	
		T34-W	19	
		T34-X	19	
KDZB				Horseshoe Bay Resort
	APCH			
		R17	40	
		R35	40	
KEGE				Eagle County Rgnl
	APCH			
		I25	40	
		L25-Y	40	
KHIF				Ogden/Hill AFB
	SID			
		DEVLN1	40	
		LGTNG1	40	
KJPX				East Hampton Town
	APCH			
		R10-M	40	
		R28-M	40	
KLSV				Las Vegas/Nellis AFB
	APCH			
		T03R	19	
		T21LX	19	
		T21LY	19	
		T21LZ	19	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
KMTC				Mount Clemens/Selfridge ANGB
	APCH			
		T01-Y	19	
		T01-Z	19	
		T19-Y	19	
		T19-Z	19	
KNDZ				Milton/Whiting Fld NAS South
	APCH			
		T32	19	
KNLC				Lemoore NAS / Reeves Fld
	SID			
		LEM2EO	40	
		REV5BU	40	
KPAM				Panama City/Tyndall AFB
	APCH			
		T14LY	19	
		T14LZ	19	
		T14RY	19	
		T32LY	19	
		T32RY	19	
		T32RZ	19	
KTCM				Tacoma/McChord Fld /Joint Bas
	STAR			
		WHYTE7	40	
KWAL				Wallops Island/Wallops Flight
	APCH			
		T10	41	
KWRB				Warner Robins/Robins AFB
	APCH			
		T15-Y	19	
		T15-Z	19	
		T33-Y	19	
		T33-Z	19	
LJCE				Cerklje ob Krki
	APCH			
		N08	22	
MMAN				Monterrey/Del Norte Intl
	APCH			
		V20-W	11	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
NWWC				Ile Art/Waala
	APCH			
		H10	5	
NZWB				Woodbourne
	STAR			
		NORTHV	27	
		WESTV	27	
OPKC				Karachi/Jinnah Intl
	APCH			
		V25LY	3	
		V25RY	3	
OPLA				Lahore/Allama Iqbal Intl
	APCH			
		V18LZ	3	
		V18RZ	3	
		V36L	3	
		V36R	3	
PAAD				Deadhorse/Point Thomson Airstr
	APCH			
		R05	40	
		R23	40	
PABP				Deadhorse/Badami
	APCH			
		R04	40	
		R22	40	
PACZ				Cape Romanzof LRRS
	APCH			
		R02	40	
PADG				Red Dog
	APCH			
		R03	40	
		R03-P	40	
	SID			
		SICOV1	40	
PADK				Adak Island/Adak
	APCH			
		R23-N	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
PADQ				Kodiak
	APCH			
		I26-Z	40	
		L26-Z	40	
PADU				Unalaska
	APCH			
		N13	40	
		N31	40	
		R13	40	
		R13-M	40	
		R31	40	
		R31-M	40	
	SID			
		DUT1	40	
PAEN				Kenai Muni
	APCH			
		R03-N	40	
		R21-N	40	
PAGB				Galbraith Lake
	APCH			
		R14	40	
	SID			
		ARTIC2	40	
PAIM				Utopia Creek/Indian Mountain L
	APCH			
		N25	40	
		R25	40	
	SID			
		CLYDD4	40	
PAJN				Juneau Intl
	APCH			
		R08-T	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
PAKU				Kuparuk/Ugnu-Kuparuk
	APCH			
		I06	40	
		I24	40	
		L06	40	
		L24	40	
		R06	40	
		R24	40	
PAKW				Klawock
	APCH			
		R02-Z	40	
PALP				Nuiqsut/Alpine Airstrip
	APCH			
		R04	40	
		R22	40	
	SID			
		NUQST1	40	
PALU				Cape Lisburne LRRS
	APCH			
		R27	40	
	SID			
		GRAAY4	40	
		LUR8	40	
PAPG				Petersburg James A Johnson
	APCH			
		R23-P	40	
	SID			
		XADZY2	40	
PAPR				Prospect Creek
	APCH			
		R01-M	40	
		R01-Z	40	
		R19	40	
	SID			
		CYCLE1	40	
PASN				St Paul Island
	APCH			
		R18-M	40	
		R36-M	40	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
PASV				Sparrevohn LRRS
	APCH			
		N35	40	
		R35	40	
PATC				Tin City LRRS
	APCH			
		Q35	40	
		R35	40	
	SID			
		HONPO3	40	
		JEKLI3	40	
		TNC5	40	
PATL				Takotna/Tatalina LRRS
	APCH			
		R35	40	
	SID			
		TLJ4	40	
PAVD				Valdez Pioneer Fld
	SID			
		FJORD1	40	
		JOH2	40	
RJBB				Kansai Intl
	STAR			
		CDO1	42	
		CDO2F	42	
		CDO2O	42	
		CDO3	42	
		CDO4	42	
RJFA				Ashiya
	APCH			
		T12	19	
RKSM				Seoul
	APCH			
		I20	22	
		I20-Z	22	
		L19	22	
		L19-Z	22	
		L20	22	
		L20-Z	22	

*See Reason Code table on page R1

	Type	Procedure	Reason*	
RKSO				Songtan-Si/Osan AB
	APCH			
		T09LZ	19	
		T09RZ	19	
		T27LZ	19	
		T27RZ	19	
TX25				Athens/Lochridge Ranch
	APCH			
		N17	40	
UNSS				Strezhevoy
	SID			
		BUNA1Z	22	
VTBK				Nakhon Pathom/Kamphaeng Saen
	APCH			
		V21	2	

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final
42	Profile descent STARs

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55