

Exclusion List for GE NavDBs in Cycle 1805

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1805. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
012		Brazil Clay County
	APCH	
	R27	5
	V09	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
AYPY		Port Moresby/Jacksons
	APCH	
	V32R	2
CYPK		Pitt Meadows
	APCH	
	R08RY	15
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

*See Reason Code table on page R1

Type	Procedure	Reason*
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
	BE08	5
EGHC		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
EGHE		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5
EGJA		St Annes/Alderney
	APCH	
	N08	5
	N26	5
EGYD		Cranwell
	SID	
	SID1B	5
ENBL		Forde/Bringeland
	APCH	
	J07	1
	J25	1
ENBN		Bronnoysund/Bronnoy
	APCH	
	J04	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J05	1
		J23	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J03	1
		J21	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETHB			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
	HB33	5	
EVRA			Riga
		APCH	
		I18-A	5
		I36-A	5
GVSV			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
KDLH			Duluth Intl
	APCH	T09	19
KDYS			Abilene/Dyess AFB
	APCH	T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
	APCH	T18	19
		T36	19
KENV			Wendover
	APCH	R08	5
KFLG			Flagstaff Pulliam
	APCH	V21	2
KGTB			Fort Drum/Wheeler-Sack AAF
	APCH	N33	5
KHTO			East Hampton
	APCH	R10-X	5
KMTC			Mount Clemens/Selfridge ANGB
	APCH	T01	19
		T19	19
KMTN			Baltimore/Martin State
	APCH	D15-Z	11
		T15-Z	11
KNDZ			Milton/Whiting Fld NAS South
	APCH	T32	19
KNJM			Swansboro/Bogue Fld Mcalf
	APCH	T23	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KNOG			Orange Grove NALF
		APCH	
		T13	19
		T31	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LDOS			Osijek/Klisa
		STAR	
		VIBO3A	11
		VIBO3B	11
LESO			San Sebastian
		SID	
		BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
LFBD			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5
LHPA			Papa AB
		APCH	
		N16	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
LIBR			Brindisi/Casale MIL
		STAR	
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
LRSV			Suceava/Stefan cel Mare - Suce
		APCH	
		R16	15
		R34	15
LTFG			Alanya/Gazipasa
		APCH	
		L08	11
LYNI			Nis/Konstantin Veliki
		APCH	
		H11	13
MMCT			Chichen-Itza Intl
		APCH	
		V10	2
		V28	2
MSSS			San Salvador/Ilopango Intl
		APCH	
		V15	5
N07			Lincoln Park
		APCH	
		R01	5
		R19	5
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NSFI			Apia/Fagali'i
	APCH		
		R10-Y	5
NTAA			Tahiti/Faa'a
	SID		
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
	SID		
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
	APCH		
		V27-X	5
NZTK			Takaka
	APCH		
		R18-Y	5
OEGT			Guriat Domestic
	APCH		
		V28	2
OERR			Arar Domestic
	APCH		
		V10	2
OIKQ			Gheshm Island/Gheshm
	STAR		
		MOBO1R	11
		MOBO1T	11
OIKR			Rafsanjan
	STAR		
		SRJ2N	11
OINN			Noshahr
	SID		
		DANE2A	11
		DANE2B	11
OITM			Maragheh/Sahand
	STAR		
		GETO1C	11

*See Reason Code table on page R1

	Type	Procedure	Reason*
RCFG			Matsu/Nangan
	STAR		
		PT1	11
RCKW			Hengchun
	STAR		
		FA1B	11
		FA1J	11
RJAH			Hyakuri
	APCH		
		I03RW	11
		I03RY	11
		I03RZ	11
		L03RW	11
		L03RY	11
		L03RZ	11
		T03LY	11
		T03LZ	11
		T03RY	11
		T03RZ	11
		T21LY	11
		T21LZ	11
		T21RY	11
		T21RZ	11
		STAR	
		GOT	11
RKSM			Seoul Domestic
	APCH		
		I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
	APCH		
		V31	2
SBPV			Porto Velho/Gov. J.T.de Olivei
	APCH		
		V01	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
SBSN			Santarem/Maestro Wilson Fonseca
		APCH	
		V10	2
		V28	2
TGPY			St Georges/Maurice Bishop Intl
		APCH	
		V10	2
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5
UKHK			Kremenchuk/Velyka Kokhnyvka Na
		APCH	
		N36	5
UUEE			Moscow/Sheremetyevo
		APCH	
		J06LY	1
		J06LZ	1
		J24R	1
UWGG			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1
UWWW			Samara/Kurumoch
		APCH	
		J15	1
		J33	1
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
VTPM			Tak/Mae Sot
		APCH	
		N27	11
WAJI			Sarmi/Orai
		APCH	
		R13	5
WAKE			Bade
		APCH	
		R02	5
		R20	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WASA			Ayawasi
		APCH	
		R09	5
		R27	5
WASI			Inanwatan
		APCH	
		R08	5
		R26	5
WAUM			Merdei/Jahabra
		APCH	
		R27	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
15	SBAS required procedure without valid Path Point record
19	procedure requires a military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55