

## Exclusion List for GE NavDBs in Cycle 1806

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1806. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
<b>012</b>		Brazil Clay County
	APCH	
	R27	5
	V09	5
<b>12N</b>		Andover/Aeroflex-Andover
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>AYPY</b>		Port Moresby/Jacksons
	APCH	
	V32R	2
<b>CYPK</b>		Pitt Meadows
	APCH	
	R08RY	15
<b>CYYT</b>		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>EBBE</b>		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
	BE08	5
<b>EGHC</b>		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
<b>EGHE</b>		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5
<b>EGJA</b>		St Annes/Alderney
	APCH	
	N08	5
	N26	5
<b>EGYD</b>		Cranwell
	SID	
	SID1B	5
<b>ENBL</b>		Forde/Bringeland
	APCH	
	J07	1
	J25	1
<b>ENBN</b>		Bronnoysund/Bronnoy
	APCH	
	J04	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENBS</b>			Batsfjord
		APCH	
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
		APCH	
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
		APCH	
		J05	1
		J23	1
<b>ENHK</b>			Hasvik
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes
		APCH	
		J20	1
<b>ENMH</b>			Mehamn
		APCH	
		J17	1
		J35	1
<b>ENMS</b>			Mosjoen/Kjaerstad
		APCH	
		J34	1
<b>ENNM</b>			Namsos
		APCH	
		J07	1
		J25	1
<b>ENRM</b>			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
<b>ENRS</b>			Rost
		APCH	
		J03	1
		J21	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENSH</b>			Svolvaer/Helle
		APCH	
		J01	1
<b>ENSK</b>			Stokmarknes/Skagen
		APCH	
		J09	1
<b>ENSS</b>			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
<b>ENST</b>			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
<b>ENVV</b>			Vadso
		APCH	
		J07	1
		J25	1
<b>EPPR</b>			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
<b>ETHB</b>			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
	HB33	5	
<b>EVRA</b>			Riga
		APCH	
		I18-A	5
		I36-A	5
<b>GVSF</b>			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KDLH</b>			Duluth Intl
	APCH		
		T09	19
<b>KDYS</b>			Abilene/Dyess AFB
	APCH		
		T16-W	19
		T34-W	19
<b>KEGI</b>			Crestview/Duke Fld, Eglin AF A
	APCH		
		T18	19
		T36	19
<b>KENV</b>			Wendover
	APCH		
		R08	5
<b>KFLG</b>			Flagstaff Pulliam
	APCH		
		V21	2
<b>KGTB</b>			Fort Drum/Wheeler-Sack AAF
	APCH		
		N33	5
<b>KHTO</b>			East Hampton
	APCH		
		R10-X	5
<b>KLSV</b>			Las Vegas/Nellis AFB
	APCH		
		T21LX	19
<b>KMTC</b>			Mount Clemens/Selfridge ANGB
	APCH		
		T01	19
		T19	19
<b>KMTN</b>			Baltimore/Martin State
	APCH		
		D15-Z	11
		T15-Z	11
<b>KNDZ</b>			Milton/Whiting Fld NAS South
	APCH		
		T32	19

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KNJM</b>			Swansboro/Bogue Fld Mcalf
		APCH	
		T23	19
<b>KNOG</b>			Orange Grove NALF
		APCH	
		T13	19
		T31	19
<b>KPAM</b>			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
<b>KVKX</b>			Friendly/Potomac Airfield
		APCH	
		R06	5
<b>KVPS</b>			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
<b>LDOS</b>			Osijek/Klisa
		STAR	
		VIBO3A	11
		VIBO3B	11
<b>LESO</b>			San Sebastian
		SID	
		BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
<b>LFBD</b>			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
<b>LHKE</b>			Kecskemet
		APCH	
		N12	5
		N30	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LHPA</b>			Papa AB
	APCH		
		N16	5
<b>LIBR</b>			Brindisi/Casale MIL
	STAR		
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
<b>LIMS</b>			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
<b>LRSV</b>			Suceava/Stefan cel Mare - Suce
	APCH		
		R16	15
		R34	15
<b>LTFG</b>			Alanya/Gazipasa
	APCH		
		L08	11
<b>LYNI</b>			Nis/Konstantin Veliki
	APCH		
		H11	13
<b>MMCT</b>			Chichen-Itza Intl
	APCH		
		V10	2
		V28	2
<b>MSSS</b>			San Salvador/Ilopango Intl
	APCH		
		V15	5
<b>N07</b>			Lincoln Park
	APCH		
		R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor
	APCH		
		R07	5
		R25	5
		V07	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>N85</b>			Pittstown/Alexandria
	APCH	D08	5
<b>NSFI</b>			Apia/Fagali'i
	APCH	R10-Y	5
<b>NTAA</b>			Tahiti/Faa'a
	SID	ARIT4E	5
		ARIT4W	5
<b>NTTE</b>			Tetiaroa
	SID	TAVI1E	5
		TAVI1W	5
<b>NTTG</b>			Rangiroa
	APCH	V27-X	5
<b>NZTK</b>			Takaka
	APCH	R18-Y	5
<b>OEGT</b>			Guriat Domestic
	APCH	V28	2
<b>OERR</b>			Arar Domestic
	APCH	V10	2
<b>OIKQ</b>			Gheshm Island/Gheshm
	STAR	MOBO1R	11
		MOBO1T	11
<b>OIKR</b>			Rafsanjan
	STAR	SRJ2N	11
<b>OINN</b>			Noshahr
	SID	DANE2A	11
		DANE2B	11

\*See Reason Code table on page R1



	Type	Procedure	Reason*
<b>OITM</b>			Maragheh/Sahand
	STAR	GETO1C	11
<b>RCFG</b>			Matsu/Nangan
	STAR	PT1	11
<b>RCKW</b>			Hengchun
	STAR	FA1B	11
		FA1J	11
<b>RKSM</b>			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SBFZ</b>			Fortaleza/Pinto Martins Intl
	APCH	V31	2
<b>SBPV</b>			Porto Velho/Gov. J.T.de Olivei
	APCH	V01	2
<b>SBSN</b>			Santarem/Maestro Wilson Fonsec
	APCH	V10	2
		V28	2
<b>TGPY</b>			St Georges/Maurice Bishop Intl
	APCH	V10	2
<b>UHPK</b>			Ust-Kamchatsk
	STAR	DOMUD2	5
<b>UKHK</b>			Kremenchuk/Velyka Kokhnyvka Na
	APCH	N36	5
<b>UUEE</b>			Moscow/Sheremetyevo
	APCH	J06LY	1
		J06LZ	1
		J24R	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>UWGG</b>			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1
<b>UWWW</b>			Samara/Kurumoch
		APCH	
		J15	1
		J33	1
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
<b>VTPM</b>			Tak/Mae Sot
		APCH	
		N27	11
<b>WAJI</b>			Sarmi/Orai
		APCH	
		R13	5
<b>WAKE</b>			Bade
		APCH	
		R02	5
		R20	5
<b>WASA</b>			Ayawasi
		APCH	
		R09	5
		R27	5
<b>WASI</b>			Inanwatan
		APCH	
		R08	5
		R26	5
<b>WAUM</b>			Merdei/Jahabra
		APCH	
		R27	5
<b>WIRR</b>			Tangerang/Budiarto
		APCH	
		V30	5

\*See Reason Code table on page R1

## Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
15	SBAS required procedure without valid Path Point record
19	procedure requires a military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55