

Exclusion List for GE NavDBs in Cycle 1807

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1807. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
012		Brazil Clay County
	APCH	
	R27	5
	V09	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
AYPY		Port Moresby/Jacksons
	APCH	
	V32R	2
CYPK		Pitt Meadows
	APCH	
	R08RY	15
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

*See Reason Code table on page R1

Type	Procedure	Reason*
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
	BE08	5
EGHC		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
EGHE		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5
EGJA		St Annes/Alderney
	APCH	
	N08	5
	N26	5
EGYD		Cranwell
	SID	
	SID1B	5
ENBL		Forde/Bringeland
	APCH	
	J07	1
	J25	1
ENBN		Bronnoysund/Bronnoy
	APCH	
	J04	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J05	1
		J23	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J03	1
		J21	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVV			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETHB			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
	HB33	5	
EVRA			Riga
		APCH	
		I18-A	5
		I36-A	5
GVSV			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
KDLH			Duluth Intl
	APCH		
		T09	19
KDYS			Abilene/Dyess AFB
	APCH		
		T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
	APCH		
		T18	19
		T36	19
KENV			Wendover
	APCH		
		R08	5
KFLG			Flagstaff Pulliam
	APCH		
		V21	2
KGTB			Fort Drum/Wheeler-Sack AAF
	APCH		
		N33	5
KHTO			East Hampton
	APCH		
		R10-X	5
KLSV			Las Vegas/Nellis AFB
	APCH		
		T21LX	19
KMTC			Mount Clemens/Selfridge ANGB
	APCH		
		T01	19
		T19	19
KMTN			Baltimore/Martin State
	APCH		
		D15-Z	11
		T15-Z	11
KNDZ			Milton/Whiting Fld NAS South
	APCH		
		T32	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KNJM			Swansboro/Bogue Fld Mcalf
		APCH	
		T23	19
KNOG			Orange Grove NALF
		APCH	
		T13	19
		T31	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LDOS			Osijek/Klisa
		STAR	
		VIBO3A	11
		VIBO3B	11
LESO			San Sebastian
		SID	
		BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
LFBD			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
LHPA			Papa AB
	APCH		
		N16	5
LIBR			Brindisi/Casale MIL
	STAR		
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
LIMS			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
LTFG			Alanya/Gazipasa
	APCH		
		L08	11
LYNI			Nis/Konstantin Veliki
	APCH		
		H11	13
MMCT			Chichen-Itza Intl
	APCH		
		V10	2
		V28	2
MSSS			San Salvador/Ilopango Intl
	APCH		
		V15	5
N07			Lincoln Park
	APCH		
		R01	5
		R19	5
N40			Pittstown/Sky Manor
	APCH		
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
	APCH		
		D08	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NSFI			Apia/Fagali'i
		APCH	
		R10-Y	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2
OIKQ			Gheshm Island/Gheshm
		STAR	
		MOBO1R	11
		MOBO1T	11
OIKR			Rafsanjan
		STAR	
		SRJ2N	11
OINN			Noshahr
		SID	
		DANE2A	11
		DANE2B	11

*See Reason Code table on page R1

	Type	Procedure	Reason*
OISY			Yasouj
	STAR	RADI1N	11
OITM			Maragheh/Sahand
	STAR	GETO1C	11
RCFG			Matsu/Nangan
	STAR	PT1	11
RCKW			Hengchun
	STAR	FA1B	11
		FA1J	11
RKSM			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
	APCH	V31	2
SBPV			Porto Velho/Gov. J.T.de Olivei
	APCH	V01	2
SBSN			Santarem/Maestro Wilson Fonsec
	APCH	V10	2
		V28	2
TGPY			St Georges/Maurice Bishop Intl
	APCH	V10	2
UHPK			Ust-Kamchatsk
	STAR	DOMUD2	5
UKHK			Kremenchuk/Velyka Kokhivka Na
	APCH	N36	5

*See Reason Code table on page R1

Type	Procedure	Reason*
UUEE		Moscow/Sheremetyevo
	APCH	
	J06LY	1
	J06LZ	1
	J24R	1
UWGG		Nizhny Novgorod/Strigino
	APCH	
	J18L	1
	J36R	1
UWWW		Samara/Kurumoch
	APCH	
	J15	1
	J33	1
VTBK		Nakhon Pathom/Kamphaeng Saen
	APCH	
	V21	2
VTPM		Tak/Mae Sot
	APCH	
	N27	11
WAJI		Sarmi/Orai
	APCH	
	R13	5
WAKE		Bade
	APCH	
	R02	5
	R20	5
WASA		Ayawasi
	APCH	
	R09	5
	R27	5
WASI		Inanwatan
	APCH	
	R08	5
	R26	5
WAUM		Merdei/Jahabra
	APCH	
	R27	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WIRR			Tangerang/Budiarto
	APCH		
	V30		5

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
15	SBAS required procedure without valid Path Point record
19	procedure requires a military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55