

Exclusion List for GE NavDBs in Cycle 1810

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1810. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
012		Brazil Clay County
	APCH	
	R27	5
	V09	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
AYPY		Port Moresby/Jacksons
	APCH	
	V32R	2
CYPK		Pitt Meadows
	APCH	
	R08RY	15
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

*See Reason Code table on page R1

Type	Procedure	Reason*
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
	BE08	5
EGHC		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
EGHE		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5
EGJA		St Annes/Alderney
	APCH	
	N08	5
	N26	5
EGYD		Cranwell
	SID	
	SID1B	5
ENBL		Forde/Bringeland
	APCH	
	J07	1
	J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
		R03-X	15
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J05	1
		J23	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENRS			Rost
		APCH	
		J03	1
		J21	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVV			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETHB			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
	HB33	5	
EVRA			Riga
		APCH	
		I18-A	5
		I36-A	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
GVSV			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22
KENV			Wendover
		APCH	
		R08	5
KGTB			Fort Drum/Wheeler-Sack AAF
		APCH	
		N33	5
KHTO			East Hampton
		APCH	
		R10-X	5
KMTN			Baltimore/Martin State
		APCH	
		D15-Z	11
		T15-Z	11
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
LDOS			Osijek/Klisa
		STAR	
		VIBO3A	11
		VIBO3B	11
LESO			San Sebastian
		SID	
		BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
LFBD			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
LHPA			Papa AB
	APCH		
		N16	5
LIBR			Brindisi/Casale MIL
	STAR		
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
LIMS			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
LTFG			Alanya/Gazipasa
	APCH		
		L08	11
MMCT			Chichen-Itza Intl
	APCH		
		V10	2
		V28	2
MSSS			San Salvador/Ilopango Intl
	APCH		
		V15	5
N07			Lincoln Park
	APCH		
		R01	5
		R19	5
N40			Pittstown/Sky Manor
	APCH		
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
	APCH		
		D08	5
NSFI			Apia/Fagali'i
	APCH		
		R10-Y	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2
OIKQ			Gheshm Island/Gheshm
		STAR	
		MOBO1R	11
		MOBO1T	11
OIKR			Rafsanjan
		STAR	
		SRJ2N	11
OINN			Noshahr
		SID	
		DANE2A	11
		DANE2B	11
OITM			Maragheh/Sahand
		STAR	
		GETO1C	11

*See Reason Code table on page R1

	Type	Procedure	Reason*
RCFG			Matsu/Nangan
	STAR		
		PT1	11
RCKW			Hengchun
	STAR		
		FA1B	11
		FA1J	11
RKSM			Seoul Domestic
	APCH		
		I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
	APCH		
		V31	2
SBPV			Porto Velho/Gov. J.T.de Olivei
	APCH		
		V01	2
SBSN			Santarem/Maestro Wilson Fonsec
	APCH		
		V10	2
		V28	2
TGPY			St Georges/Maurice Bishop Intl
	APCH		
		V10	2
UHPK			Ust-Kamchatsk
	STAR		
		DOMUD2	5
UKHK			Kremenchuk/Velyka Kokhnyvka Na
	APCH		
		N36	5
UUEE			Moscow/Sheremetyevo
	APCH		
		J06LY	1
		J06LZ	1
		J24R	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
UWGG			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1
UWWW			Samara/Kurumoch
		APCH	
		J15	1
		J33	1
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
VTPM			Tak/Mae Sot
		APCH	
		N27	11
WAJI			Sarmi/Orai
		APCH	
		R13	5
WAKE			Bade
		APCH	
		R02	5
		R20	5
WASA			Ayawasi
		APCH	
		R09	5
		R27	5
WASI			Inanwatan
		APCH	
		R08	5
		R26	5
WAUM			Merdei/Jahabra
		APCH	
		R27	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
15	SBAS required procedure without valid Path Point record
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55