

## Exclusion List for GE NavDBs in Cycle 1811

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1811. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
<b>012</b>		Brazil Clay County
	APCH	
	R27	5
	V09	5
<b>12N</b>		Andover/Aeroflex-Andover
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>AYPY</b>		Port Moresby/Jacksons
	APCH	
	V32R	2
<b>CYPK</b>		Pitt Meadows
	APCH	
	R08RY	15
<b>CYYT</b>		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>EBBE</b>		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
	BE08	5
<b>EGHC</b>		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
<b>EGHE</b>		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5
<b>EGJA</b>		St Annes/Alderney
	APCH	
	N08	5
	N26	5
<b>EGYD</b>		Cranwell
	SID	
	SID1B	5
<b>ENBL</b>		Forde/Bringeland
	APCH	
	J07	1
	J25	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENBN</b>			Bronnoysund/Bronnoy
		APCH	
		J03	1
		R03-X	15
<b>ENBS</b>			Batsfjord
		APCH	
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
		APCH	
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
		APCH	
		J05	1
		J23	1
<b>ENHK</b>			Hasvik
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes
		APCH	
		J20	1
<b>ENMH</b>			Mehamn
		APCH	
		J17	1
		J35	1
<b>ENMS</b>			Mosjoen/Kjaerstad
		APCH	
		J34	1
<b>ENNM</b>			Namsos
		APCH	
		J07	1
		J25	1
<b>ENRM</b>			Rorvik/Ryum
		APCH	
		J04	1
		J22	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENRS</b>			Rost
		APCH	
		J03	1
		J21	1
<b>ENSH</b>			Svolvaer/Helle
		APCH	
		J01	1
<b>ENSK</b>			Stokmarknes/Skagen
		APCH	
		J09	1
<b>ENSS</b>			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
<b>ENST</b>			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
<b>ENVD</b>			Vadso
		APCH	
		J07	1
		J25	1
<b>EPPR</b>			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
<b>ETHB</b>			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
	HB33	5	
<b>EVRA</b>			Riga
		APCH	
		I18-A	5
		I36-A	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>GVSV</b>			Sao Pedro/Sao Vicente/Cesaria
	SID	SNT1G	22
<b>KENV</b>			Wendover
	APCH	R08	5
<b>KHTO</b>			East Hampton
	APCH	R10-X	5
<b>KMTN</b>			Baltimore/Martin State
	APCH	D15-Z	11
		T15-Z	11
<b>KVKX</b>			Friendly/Potomac Airfield
	APCH	R06	5
<b>LDOS</b>			Osijek/Klisa
	STAR	VIBO3A	11
		VIBO3B	11
<b>LESO</b>			San Sebastian
	SID	BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
<b>LFBD</b>			Bordeaux/Merignac
	SID	ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
<b>LHKE</b>			Kecskemet
	APCH	N12	5
		N30	5
<b>LHPA</b>			Papa AB
	APCH	N16	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LIBR</b>			Brindisi/Casale MIL
		STAR	
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
<b>LIMS</b>			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
<b>LTFG</b>			Alanya/Gazipasa
		APCH	
		L08	11
<b>MMCT</b>			Chichen-Itza Intl
		APCH	
		V10	2
		V28	2
<b>MSSS</b>			San Salvador/Ilopango Intl
		APCH	
		V15	5
<b>N07</b>			Lincoln Park
		APCH	
		R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
<b>N85</b>			Pittstown/Alexandria
		APCH	
		D08	5
<b>NSFI</b>			Apia/Fagali'i
		APCH	
		R10-Y	5
<b>NTAA</b>			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>NTTE</b>			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
<b>NTTG</b>			Rangiroa
		APCH	
		V27-X	5
<b>NZTK</b>			Takaka
		APCH	
		R18-Y	5
<b>NZWB</b>			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
<b>OEGT</b>			Guriat Domestic
		APCH	
		V28	2
<b>OERR</b>			Arar Domestic
		APCH	
		V10	2
<b>OIKQ</b>			Gheshm Island/Gheshm
		STAR	
		MOBO1R	11
		MOBO1T	11
<b>OIKR</b>			Rafsanjan
		STAR	
		SRJ2N	11
<b>OINN</b>			Noshahr
		SID	
		DANE2A	11
		DANE2B	11
<b>OITM</b>			Maragheh/Sahand
		STAR	
		GETO1C	11
<b>RCFG</b>			Matsu/Nangan
		STAR	
		PT1	11

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>RCKW</b>			Hengchun
		STAR	
		FA1B	11
		FA1J	11
<b>RKSM</b>			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SBFZ</b>			Fortaleza/Pinto Martins Intl
		APCH	
		V31	2
<b>SBPV</b>			Porto Velho/Gov. J.T.de Olivei
		APCH	
		V01	2
<b>SBSN</b>			Santarem/Maestro Wilson Fonsec
		APCH	
		V10	2
		V28	2
<b>TGPY</b>			St Georges/Maurice Bishop Intl
		APCH	
		V10	2
<b>UHPK</b>			Ust-Kamchatsk
		STAR	
		DOMUD2	5
<b>UKHK</b>			Kremenchuk/Velyka Kokhnyvka Na
		APCH	
		N36	5
<b>UUEE</b>			Moscow/Sheremetyevo
		APCH	
		J06LY	1
		J06LZ	1
		J24R	1
<b>UWGG</b>			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1

\*See Reason Code table on page R1



	Type	Procedure	Reason*
<b>UWWW</b>			Samara/Kurumoch
		APCH	
		J15	1
		J33	1
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
<b>VTPM</b>			Tak/Mae Sot
		APCH	
		N27	11
<b>VTSE</b>			Chumphon
		APCH	
		V06	2
		V24	2
<b>WAJI</b>			Sarmi/Orai
		APCH	
		R13	5
<b>WAKE</b>			Bade
		APCH	
		R02	5
		R20	5
<b>WASA</b>			Ayawasi
		APCH	
		R09	5
		R27	5
<b>WASI</b>			Inanwatan
		APCH	
		R08	5
		R26	5
<b>WAUM</b>			Merdei/Jahabra
		APCH	
		R27	5
<b>WIRR</b>			Tangerang/Budiarto
		APCH	
		V30	5
<b>ZYTX</b>			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

\*See Reason Code table on page R1

## Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
15	SBAS required procedure without valid Path Point record
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55