

## Exclusion List for GE NavDBs in Cycle 1813

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1813. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>AYPY</b>		Port Moresby/Jacksons
	APCH	
	V32R	2
<b>CYPK</b>		Pitt Meadows
	APCH	
	R08RY	15
<b>CYYT</b>		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
<b>EBBE</b>		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	T22RY	5
	SID	
	BE05	5
	BE06	5
	BE07	5
BE08	5	
<b>EGYD</b>		Cranwell
	SID	
	SID1B	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENBL</b>			Forde/Bringeland
		APCH	
		J07	1
		J25	1
<b>ENBN</b>			Bronnoysund/Bronnoy
		APCH	
		J03	1
		R03-X	15
<b>ENBS</b>			Batsfjord
		APCH	
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
		APCH	
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
		APCH	
		J05	1
		J23	1
<b>ENHK</b>			Hasvik
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes
		APCH	
		J20	1
<b>ENMH</b>			Mehamn
		APCH	
		J17	1
		J35	1
<b>ENMS</b>			Mosjoen/Kjaerstad
		APCH	
		J34	1
<b>ENNM</b>			Namsos
		APCH	
		J07	1
		J25	1

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>ENRM</b>		Rorvik/Ryum
	APCH	
	J04	1
	J22	1
<b>ENRS</b>		Rost
	APCH	
	J03	1
	J21	1
<b>ENSH</b>		Svolvaer/Helle
	APCH	
	J01	1
<b>ENSK</b>		Stokmarknes/Skagen
	APCH	
	J09	1
<b>ENSS</b>		Vardo/Svartnes
	APCH	
	J15	1
	J33	1
<b>ENST</b>		Stokka/Sandnessjoen
	APCH	
	J02	1
	J20	1
<b>ENVD</b>		Vadso
	APCH	
	J07	1
	J25	1
<b>EPPR</b>		Pruszcz Gdanski
	APCH	
	N27-X	5
	N27-Y	5
	N27-Z	5
<b>ETHB</b>		Buckeburg
	SID	
	HB11	5
	HB12	5
	HB13	5
	HB31	5
	HB32	5
HB33	5	

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>EVRA</b>			Riga
		APCH	
		I18-A	5
		I36-A	5
<b>GVSV</b>			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22
<b>KENV</b>			Wendover
		APCH	
		R08	5
<b>KHTO</b>			East Hampton
		APCH	
		R10-X	5
<b>KMTN</b>			Baltimore/Martin State
		APCH	
		D15-Z	11
		T15-Z	11
<b>LDOS</b>			Osijek/Klisa
		STAR	
		VIBO3A	11
		VIBO3B	11
<b>LESO</b>			San Sebastian
		SID	
		BLV1Y	11
		BTZ1Y	11
		CEGA1Z	11
		PPN1Z	11
<b>LFBD</b>			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
<b>LHKE</b>			Kecskemet
		APCH	
		N12	5
		N30	5
<b>LHPA</b>			Papa AB
		APCH	
		N16	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LIBR</b>			Brindisi/Casale MIL
		STAR	
		ABAD1J	11
		GOKE1J	11
		ORSO1J	11
<b>LIMS</b>			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
<b>LTFG</b>			Alanya/Gazipasa
		APCH	
		L08	11
<b>MMCT</b>			Chichen-Itza Intl
		APCH	
		V10	2
		V28	2
<b>MSSS</b>			San Salvador/Ilopango Intl
		APCH	
		V15	5
<b>NTAA</b>			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
<b>NTTG</b>			Rangiroa
		APCH	
		V27-X	5
<b>NZWB</b>			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
<b>OEGT</b>			Guriat Domestic
		APCH	
		V28	2
<b>OERR</b>			Arar Domestic
		APCH	
		V10	2

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>OIKQ</b>			Gheshm Island/Gheshm
		STAR	
		MOBO1R	11
		MOBO1T	11
<b>OIKR</b>			Rafsanjan
		STAR	
		SRJ2N	11
<b>OINN</b>			Noshahr
		SID	
		DANE2A	11
		DANE2B	11
<b>OITM</b>			Maragheh/Sahand
		STAR	
		GETO1C	11
<b>RCFG</b>			Matsu/Nangan
		STAR	
		PT1	11
<b>RCKW</b>			Hengchun
		STAR	
		FA1B	11
		FA1J	11
<b>RKSM</b>			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SBFZ</b>			Fortaleza/Pinto Martins Intl
		APCH	
		V31	2
<b>SBPV</b>			Porto Velho/Gov. J.T.de Olivei
		APCH	
		V01	2
<b>SBSN</b>			Santarem/Maestro Wilson Fonsec
		APCH	
		V10	2
		V28	2
<b>TGPY</b>			St Georges/Maurice Bishop Intl
		APCH	
		V10	2

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>UHPK</b>			Ust-Kamchatsk
	STAR	DOMUD2	5
<b>UIUU</b>			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR	BULE5H	5
		OSTU5H	5
		RIDL5H	5
		TOLG5H	5
	<b>UUEE</b>		
APCH		J06LY	1
		J06LZ	1
		J24R	1
<b>UWGG</b>			Nizhny Novgorod/Strigino
	APCH	J18L	1
		J36R	1
<b>UWWW</b>			Samara/Kurumoch
	APCH	J15	1
		J33	1
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
<b>VTPM</b>			Tak/Mae Sot
	APCH	N27	11
<b>WIRR</b>			Tangerang/Budiarto
	APCH	V30	5
<b>ZGSD</b>			Zhuhai/Jinwan
	STAR	F02A	22

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>ZYTX</b>		Shenyang/Taoxian
	STAR	
	ANS02A	22
	TOS02A	22

\*See Reason Code table on page R1



## Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
15	SBAS required procedure without valid Path Point record
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55