

Exclusion List for GE NavDBs in Cycle 1905

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1905. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
012		Brazil Clay County
	APCH	
	R27	5
	V09	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
AYPY		Port Moresby/Jacksons
	APCH	
	V32R	2
CYPK		Pitt Meadows
	APCH	
	R08RY	15
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

*See Reason Code table on page R1

Type	Procedure	Reason*
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	SID	
	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5
EBBL		Kleine Brogel
	SID	
	BL05A	22
	BL05B	22
	BL05D	22
EBFS		Florennes
	SID	
	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22
EGHC		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
EGHE		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGJA			St Annes/Alderney
		APCH	
		N08	5
		N26	5
EGYD			Cranwell
		SID	
		SID1B	5
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
		R03-X	15
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J05	1
		J23	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J03	1
		J21	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5

*See Reason Code table on page R1

Type	Procedure	Reason*
ETHB		Buckeburg
	SID	
	HB11	5
	HB12	5
	HB13	5
	HB31	5
	HB32	5
	HB33	5
ETNG		Geilenkirchen
	SID	
	NG227	22
EVRA		Riga
	APCH	
	I18-A	5
	I36-A	5
GVSV		Sao Pedro/Sao Vicente/Cesaria
	SID	
	SNT1G	22
KENV		Wendover
	APCH	
	R08	5
KHTO		East Hampton
	APCH	
	R10-X	5
KMTN		Baltimore/Martin State
	APCH	
	D15-Z	11
	T15-Z	11
KVKX		Friendly/Potomac Airfield
	APCH	
	R06	5
LDOS		Osijek/Klisa
	STAR	
	VIBO4B	11

*See Reason Code table on page R1

Type	Procedure	Reason*
LESO		San Sebastian
	SID	
	BLV1Y	11
	BTZ1Y	11
	CEGA2Z	11
	PPN1Z	11
LFBD		Bordeaux/Merignac
	SID	
	ROYA4Z	5
	SAU4Z	5
	VAVI4Z	5
LHKE		Kecskemet
	APCH	
	N12	5
	N30	5
LHPA		Papa AB
	APCH	
	N16	5
LIBR		Brindisi/Casale MIL
	STAR	
	ABAD1J	11
	GOKE1J	11
	ORSO1J	11
LIMS		Piacenza
	SID	
	GEN6Q	22
	KALM6Q	22
LTFG		Alanya/Gazipasa
	APCH	
	L08	11
MMCT		Chichen-Itza Intl
	APCH	
	V10	2
	V28	2
MSSS		San Salvador/Ilopango Intl
	APCH	
	V15	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
N07			Lincoln Park
		APCH	
		R01	5
		R19	5
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5
NSFI			Apia/Fagali'i
		APCH	
		R10-Y	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
OIKQ			Gheshm Island/Gheshm
		STAR	
		MOBO1R	11
		MOBO1T	11
OIKR			Rafsanjan
		STAR	
		SRJ2N	11
OINN			Noshahr
		SID	
		DANE2A	11
		DANE2B	11
OITM			Maragheh/Sahand
		STAR	
		GETO1C	11
RCFG			Matsu/Nangan
		STAR	
		PT1	11
RCKW			Hengchun
		STAR	
		FA1B	11
		FA1J	11
RJNG			Gifu
		APCH	
		T28	11
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
SARC			Corrientes
		APCH	
		V20	2
SBFZ			Fortaleza/Pinto Martins Intl
		APCH	
		V31	2
SBPV			Porto Velho/Gov. J.T.de Olivei
		APCH	
		V01	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
SBSN			Santarem/Maestro Wilson Fonsec
		APCH	
		V10	2
		V28	2
TGPY			St Georges/Maurice Bishop Intl
		APCH	
		V10	2
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5
UIUU			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
	RIDL5H	5	
	TOLG5H	5	
UKHK			Kremenchuk/Velyka Kokhnyvka Na
		APCH	
		N36	5
URRT			Taganrog/Yuzhny
		APCH	
		N10-X	5
		N28-X	5
UUEE			Moscow/Sheremetyevo
		APCH	
		J06L	1
		J24R	1
UWGG			Nizhny Novgorod/Strigino
		APCH	
		J18L	1
		J36R	1
UWWW			Samara/Kurumoch
		APCH	
		J15	1
		J33	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
VMMC			Macao Intl
	APCH	H16	13
VTBK			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
VTPM			Tak/Mae Sot
	APCH	N27	11
WAJI			Sarmi/Orai
	APCH	R13	5
WAKE			Bade
	APCH	R02	5
		R20	5
WASA			Ayawasi
	APCH	R09	5
		R27	5
WASI			Inanwatan
	APCH	R08	5
		R26	5
WAUM			Merdei/Jahabra
	APCH	R27	5
WAYK			Kokonao
	APCH	H13	5
WIRR			Tangerang/Budiarto
	APCH	V30	5
ZGSD			Zhuhai/Jinwan
	STAR	F02A	22
ZSPD			Shanghai/Pudong
	STAR	AND15A	27

*See Reason Code table on page R1

Type	Procedure	Reason*
ZYTX		Shenyang/Taoxian
	STAR	
	ANS02A	22
	TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
15	SBAS required procedure without valid Path Point record
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55