

Exclusion List for GE NavDBs in Cycle 1906

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 1906. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
	V08	5
012		Brazil Clay County
	APCH	
	R27	5
	V09	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
AYPY		Port Moresby/Jacksons
	APCH	
	V32R	2
CYPK		Pitt Meadows
	APCH	
	R08RY	15
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5

*See Reason Code table on page R1

Type	Procedure	Reason*
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
	SID	
	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5
EBBL		Kleine Brogel
	SID	
	BL05A	22
	BL05B	22
	BL05D	22
EBFS		Florennes
	SID	
	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22
EGHC		Penzance/Lands End
	APCH	
	R07	5
	R16	5
	R25	5
	R34	5
EGHE		St Mary's/Scilly Isles
	APCH	
	N27	5
	N32	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGJA			St Annes/Alderney
		APCH	
		N08	5
		N26	5
EGYD			Cranwell
		SID	
		SID1B	5
EHEH			Eindhoven
		SID	
		EH5	22
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
		R03-X	15
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J05	1
		J23	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETHB			Buckeburg
		SID	
		HB11	5
		HB12	5
		HB13	5
		HB31	5
		HB32	5
		HB33	5
ETNG			Geilenkirchen
		SID	
		NG227	22
EVRA			Riga
		APCH	
		I18-A	5
		I36-A	5
GVSV			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KMTN			Baltimore/Martin State
		APCH	
		D15-Z	31
		T15-Z	31
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5

*See Reason Code table on page R1

Type	Procedure	Reason*
LFBD		Bordeaux/Merignac
	SID	
	ROYA4Z	5
	SAU4Z	5
	VAVI4Z	5
LHKE		Kecskemet
	APCH	
	N12	5
	N30	5
LHPA		Papa AB
	APCH	
	N16	5
LIMS		Piacenza
	SID	
	GEN6Q	22
	KALM6Q	22
MMCT		Chichen-Itza Intl
	APCH	
	V10	2
	V28	2
MSSS		San Salvador/Ilopango Intl
	APCH	
	V15	5
N07		Lincoln Park
	APCH	
	R01	5
	R19	5
N40		Pittstown/Sky Manor
	APCH	
	R07	5
	R25	5
	V07	5
N85		Pittstown/Alexandria
	APCH	
	D08	5
NSFI		Apia/Fagali'i
	APCH	
	R10-Y	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
SARC			Corrientes
		APCH	
		V20	2
SBFZ			Fortaleza/Pinto Martins Intl
		APCH	
		V31	2
SBSN			Santarem/Maestro Wilson Fonsec
		APCH	
		V10	2
		V28	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
TGPY			St Georges/Maurice Bishop Intl
	APCH	V10	2
UHPK			Ust-Kamchatsk
	STAR	DOMUD2	5
UIUU			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR	BULE5H	5
		OSTU5H	5
		RIDL5H	5
		TOLG5H	5
UKHK			Kremenchuk/Velyka Kokhnyvka Na
	APCH	N36	5
URRT			Taganrog/Yuzhny
	APCH	N10-X	5
		N28-X	5
UWGG			Nizhny Novgorod/Strigino
	APCH	J18L	1
		J36R	1
UWWW			Samara/Kurumoch
	APCH	J15	1
		J33	1
VTBK			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
WAJI			Sarmi/Orai
	APCH	R13	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAKE			Bade
		APCH	
		R02	5
		R20	5
WASA			Ayawasi
		APCH	
		R09	5
		R27	5
WASI			Inanwatan
		APCH	
		R08	5
		R26	5
WAUM			Merdei/Jahabra
		APCH	
		R27	5
WAYK			Kokonao
		APCH	
		H13	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5
ZGSD			Zhuhai/Jinwan
		STAR	
		F02A	22
ZSPD			Shanghai/Pudong
		STAR	
		AND15A	27
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
15	SBAS required procedure without valid Path Point record
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55