

Exclusion List for HWL NavDBs in Cycle 2012

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2012. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID		
-----	--	--

	BE04C	5
--	-------	---

	BE04D	5
--	-------	---

	BE22C	5
--	-------	---

	BE22D	5
--	-------	---

EBBL

Kleine Brogel

SID		
-----	--	--

	BL05A	22
--	-------	----

	BL05B	22
--	-------	----

	BL05D	22
--	-------	----

EBFS

Florennes

SID		
-----	--	--

	FS08A	22
--	-------	----

	FS08B	22
--	-------	----

	FS08C	22
--	-------	----

	FS26A	22
--	-------	----

	FS26B	22
--	-------	----

	FS26C	22
--	-------	----

EGHC

Penzance/Lands End

APCH		
------	--	--

	H07	5
--	-----	---

	H16	5
--	-----	---

	H25	5
--	-----	---

	H34	5
--	-----	---

EGHE

St Mary's/Scilly Isles

APCH		
------	--	--

	N27	5
--	-----	---

	N32	5
--	-----	---

EGJA

St Annes/Alderney

APCH		
------	--	--

	N08	5
--	-----	---

	N26	5
--	-----	---

EGNV

Teesside International

APCH		
------	--	--

	N23	3
--	-----	---

EGPO

Stornoway

APCH		
------	--	--

	L36	3
--	-----	---

	N36	3
--	-----	---

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGTE			Exeter
	APCH	N26	3
EGYD			Cranwell
	SID	SID1B	5
EHEH			Eindhoven
	SID	EH5	22
ENBL			Forde/Bringeland
	APCH	J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH	J03	1
ENBS			Batsfjord
	APCH	J03	1
		J21	1
ENBV			Berlevag
	APCH	J06	1
		J24	1
ENHF			Hammerfest
	APCH	J04	1
		J22	1
ENHK			Hasvik
	APCH	J11	1
		J29	1
ENLK			Leknes
	APCH	J20	1
ENMH			Mehamn
	APCH	J17	1
		J35	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVV			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG13	11
		NG227	22
		NG33	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
KDLH			Duluth Intl
		APCH	
		T09	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18	19
		T36	19
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KLSV			Las Vegas/Nellis AFB
		APCH	
		T21LX	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LFBD			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5
LHPA			Papa AB
		APCH	
		N16	5
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
MRLB			Liberia/Daniel Oduber Quiros I
		APCH	
		V07	2
MSSS			San Salvador/Ilopango Intl
		APCH	
		V15	5
N07			Lincoln Park
		APCH	
		R01	5
		R19	5

*See Reason Code table on page R1

Type	Procedure	Reason*
N40		Pittstown/Sky Manor
	APCH	
	R07	5
	R25	5
	V07	5
N85		Pittstown/Alexandria
	APCH	
	D08	5
NTAA		Tahiti/Faa'a
	SID	
	ARIT4E	5
	ARIT4W	5
NTTE		Tetiaroa
	SID	
	TAVI1E	5
	TAVI1W	5
NTTG		Rangiroa
	APCH	
	V27-X	5
NZTK		Takaka
	APCH	
	R18-Y	5
NZWB		Woodbourne
	STAR	
	NORTHV	27
	WESTV	27
OEGT		Guriat Domestic
	APCH	
	V28	2
OERR		Arar Domestic
	APCH	
	V10	2
OPLA		Lahore/Allama Iqbal Intl
	APCH	
	V18LZ	3
	V18RZ	3
	V36L	3
	V36R	3

*See Reason Code table on page R1

	Type	Procedure	Reason*
OPRK			Rahim Yar Khan/Sheikh Zayed In
	APCH	V01	3
PARS			Russian Mission
	APCH	R36	5
RKSM			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
	APCH	V31	2
SKUL			Tulua/Heriberto Gil Martinez
	APCH	V02	5
UHPK			Ust-Kamchatsk
	STAR	DOMUD2	5
UIUU			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR	BULE5H	5
		OSTU5H	5
		RIDL5H	5
		TOLG5H	5
URRT			Taganrog/Yuzhny
	APCH	N10-X	5
		N28-X	5
UWGG			Nizhny Novgorod/Strigino
	APCH	J18L	1
		J36R	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
VTBK			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
WAJI			Sarmi/Orai
	APCH	R13	5
WAKE			Bade
	APCH	R02	5
		R20	5
WASA			Ayawasi
	APCH	R09	5
		R27	5
WASI			Inanwatan
	APCH	H08	5
		H26	5
WAUM			Merdei/Jahabra
	APCH	R27	5
WAYK			Kokonao
	APCH	H13	5
WIRR			Tangerang/Budiarto
	APCH	V30	5
ZYTX			Shenyang/Taoxian
	STAR	ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55