

Exclusion List for HWL NavDBs in Cycle 2101

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2101. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

	Type	Procedure	Reason*
06N			Middletown/Randall
		APCH	
		R08	5
		R26	5
012			Brazil Clay County
		APCH	
		R27	5
12N			Andover/Aeroflex-Andover
		APCH	
		R03	5
2W2			Westminster/Clairview Airpark
		APCH	
		R14	5
9A5			Lafayette/Barwick Lafayette
		APCH	
		R02	5
		R20	5
CYYT			St Johns Intl
		APCH	
		R11-X	5
		R16-X	5
EBBE			Beauvechain
		APCH	
		I22RX	5
		I22RY	5
		L22RX	5
		L22RY	5
		T04LY	5
		T04R	5
	T22L	5	

*See Reason Code table on page R1

Type Procedure Reason*

SID

BE04C 5

BE04D 5

BE22C 5

BE22D 5

EBBL

Kleine Brogel

SID

BL05A 22

BL05B 22

BL05D 22

EBFS

Florennes

SID

FS08A 22

FS08B 22

FS08C 22

FS26A 22

FS26B 22

FS26C 22

EGHC

Penzance/Lands End

APCH

H07 5

H16 5

H25 5

H34 5

EGHE

St Mary's/Scilly Isles

APCH

N27 5

N32 5

EGJA

St Annes/Alderney

APCH

N08 5

N26 5

EGNV

Teesside International

APCH

N23 3

EGPO

Stornoway

APCH

L36 3

N36 3

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGTE			Exeter
	APCH		
		N26	3
EGYD			Cranwell
	SID		
		SID1B	5
EHEH			Eindhoven
	SID		
		EH5	22
ENBL			Forde/Bringeland
	APCH		
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH		
		J03	1
ENBS			Batsfjord
	APCH		
		J03	1
		J21	1
ENBV			Berlevag
	APCH		
		J06	1
		J24	1
ENHF			Hammerfest
	APCH		
		J04	1
		J22	1
ENHK			Hasvik
	APCH		
		J11	1
		J29	1
ENLK			Leknes
	APCH		
		J20	1
ENMH			Mehamn
	APCH		
		J17	1
		J35	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG13	11
		NG227	22
		NG33	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
KDLH			Duluth Intl
		APCH	
		T09	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18	19
		T36	19
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KLSV			Las Vegas/Nellis AFB
		APCH	
		T21LX	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LFBD			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5
LHPA			Papa AB
		APCH	
		N16	5
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
MMTO			Toluca/Lic Adolfo L Mateos Int
		APCH	
		H15	13
		H33	13
MRLB			Liberia/Daniel Oduber Quiros I
		APCH	
		V07	2
MSSS			San Salvador/Ilopango Intl
		APCH	
		V15	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
N07			Lincoln Park
		APCH	
		R01	5
		R19	5
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
	V36R	3	
OPRK			Rahim Yar Khan/Sheikh Zayed In
		APCH	
	V01	3	
PARS			Russian Mission
		APCH	
	R36	5	
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
	L20-Z	22	
SBFZ			Fortaleza/Pinto Martins Intl
		APCH	
	V31	2	
SKUL			Tulua/Heriberto Gil Martinez
		APCH	
	V02	5	
UHPK			Ust-Kamchatsk
		STAR	
	DOMUD2	5	
UIUU			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
URML		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
URRT		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
UWKD		Kazan
	APCH	
VTBK		Nakhon Pathom/Kamphaeng Saen
	APCH	
WAJI		Sarmi/Orai
	APCH	
WAKE		Bade
	APCH	
	R02	5
WASA		Ayawasi
	APCH	
	R09	5
WASI		Inanwatan
	APCH	
	H08	5
WAUM		Merdei/Jahabra
	APCH	
	R27	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAYK			Kokonao
		APCH	
		H13	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55