

Exclusion List for GE NavDBs in Cycle 2107

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 2107. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

EBBL

Kleine Brogel

SID		
	BL05A	22
	BL05B	22
	BL05D	22

EBFS

Florennes

SID		
	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

EGHC

Penzance/Lands End

APCH		
	H07	5
	H16	5
	H25	5
	H34	5

EGHE

St Mary's/Scilly Isles

APCH		
	N27	5
	N32	5

EGJA

St Annes/Alderney

APCH		
	N08	5
	N26	5

EGYD

Cranwell

SID		
	SID1B	5

EHEH

Eindhoven

SID		
	EH5	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04	1
		J22	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J08	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG227	22
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
	SID		
		LEP1E	5
		LEP1G	5
KENV			Wendover
	APCH		
		R08	5
KHTO			East Hampton
	APCH		
		R10-X	5
KMTN			Baltimore/Martin State
	APCH		
		T15	31
		V15	31
KVKX			Friendly/Potomac Airfield
	APCH		
		R06	5
LFBD			Bordeaux/Merignac
	SID		
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
	APCH		
		N12	5
		N30	5
LHPA			Papa AB
	APCH		
		N16	5
LIMS			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
MHTG			Tegucigalpa/Toncontin Intl
	APCH		
		H20	13
MPRA			Contadora/Cnel. Raul Arias Esp
	APCH		
		R18	21

*See Reason Code table on page R1

	Type	Procedure	Reason*
MRLB			Liberia/Daniel Oduber Quiros I
	APCH	V07	2
MSSS			San Salvador/Ilopango Intl
	APCH	V15	5
N07			Lincoln Park
	APCH	R01	5
		R19	5
N40			Pittstown/Sky Manor
	APCH	R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
	APCH	D08	5
NTAA			Tahiti/Faa'a
	SID	ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
	SID	TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
	APCH	V27-X	5
NZTK			Takaka
	APCH	R18-Y	5
NZWB			Woodbourne
	STAR	NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
	APCH	V28	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
OERR			Arar Domestic
	APCH	V10	2
PARS			Russian Mission
	APCH	R36	5
RKSM			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
RKSO			Songtan-Si/Osan AB
	APCH	H27L	13
SBFZ			Fortaleza/Pinto Martins Intl
	APCH	V31	2
SBKP			Campinas/Viracopos Intl
	APCH	H15-Y	13
SKUL			Tulua/Heriberto Gil Martinez
	APCH	V02	5
UHHM			Chegdomyn
	APCH	H13	5
		H31	5
UHPK			Ust-Kamchatsk
	STAR	DOMUD2	5
UIUU			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5

*See Reason Code table on page R1

Type Procedure Reason*

STAR

BULE5H 5

OSTU5H 5

RIDL5H 5

TOLG5H 5

UKHK

Kremenchuk/Velyka Kokhnivka

APCH

N18 5

N36 5

URML

Makhachkala/Uytash

SID

H1A 5

TA1A 5

STAR

BUIK1E 5

BUIK1G 5

GUDE1E 5

GUDE1G 5

URRT

Taganrog/Yuzhny

APCH

N10-X 5

N28-X 5

UWKD

Kazan

APCH

V11-X 5

UWSK

Krasny Kut

SID

X003 5

X070 5

X107 5

X130 5

X156 5

X267 5

X312 5

X351 5

VTBK

Nakhon Pathom/Kamphaeng Saen

APCH

V21 2

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAJI			Sarmi/Mararena
		APCH	
		H13	5
		H31	5
WAKE			Mappi/Bade
		APCH	
		H02	5
		H20	5
WASA			Maybrat/Ayawasi
		APCH	
		H09	5
		H27	5
WASI			Inanwatan
		APCH	
		H08	5
		H26	5
WAUM			Merdey
		APCH	
		H27	5
WAYK			Kokonao
		APCH	
		H13	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
21	Circling approach not compatible with FMS requirements
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55