

## Exclusion List for HWL NavDBs in Cycle 2107

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2107. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall,
	APCH	
	R08	5
	R26	5
<b>012</b>		Brazil Clay County,
	APCH	
	R27	5
<b>12N</b>		Andover/Aeroflex-Andover,
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark,
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette,
	APCH	
	R02	5
	R20	5
<b>CYYT</b>		St Johns Intl,
	APCH	
	R11-X	5
	R16-X	5
<b>EBBE</b>		Beauvechain,
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

\*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

**EBBL**

Kleine Brogel,

Type	Procedure	Reason*
SID	BL05A	22
	BL05B	22
	BL05D	22

**EBFS**

Florennes,

Type	Procedure	Reason*
SID	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

**EGHC**

Penzance/Lands End,

Type	Procedure	Reason*
APCH	H07	5
	H16	5
	H25	5
	H34	5

**EGHE**

St Mary's/Scilly Isles,

Type	Procedure	Reason*
APCH	N27	5
	N32	5

**EGJA**

St Annes/Alderney,

Type	Procedure	Reason*
APCH	N08	5
	N26	5

**EGNH**

Blackpool,

Type	Procedure	Reason*
APCH	N10	3

**EGNV**

Teesside International,

Type	Procedure	Reason*
APCH	N23	3

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>EGPO</b>			Stornoway,
		APCH	
		L36	3
		N36	3
<b>EGTE</b>			Exeter,
		APCH	
		N26	3
<b>EGYD</b>			Cranwell,
		SID	
		SID1B	5
<b>EHEH</b>			Eindhoven,
		SID	
		EH5	22
<b>ENBL</b>			Forde/Bringeland,
		APCH	
		J07	1
		J25	1
<b>ENBN</b>			Bronnoysund/Bronnoy,
		APCH	
		J03	1
<b>ENBS</b>			Batsfjord,
		APCH	
		J03	1
		J21	1
<b>ENBV</b>			Berlevag,
		APCH	
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest,
		APCH	
		J04	1
		J22	1
<b>ENHK</b>			Hasvik,
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes,
		APCH	
		J20	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENMH</b>			Mehamn,
		APCH	
		J17	1
		J35	1
<b>ENNM</b>			Namsos,
		APCH	
		J07	1
		J25	1
<b>ENRM</b>			Rorvik/Ryum,
		APCH	
		J04	1
		J22	1
<b>ENRS</b>			Rost,
		APCH	
		J02	1
		J20	1
<b>ENSH</b>			Svolvaer/Helle,
		APCH	
		J01	1
<b>ENSS</b>			Vardo/Svartnes,
		APCH	
		J15	1
		J33	1
<b>ENST</b>			Stokka/Sandnessjoen,
		APCH	
		J02	1
		J20	1
<b>ENVD</b>			Vadso,
		APCH	
		J07	1
		J25	1
<b>EPPR</b>			Pruszcz Gdanski,
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
<b>ETNG</b>			Geilenkirchen,
		SID	
		NG227	22

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>EVLA</b>			Liepaja,
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
<b>HLLM</b>			Tripoli/Mitiga Intl,
		APCH	
		D10	2
		D28	2
<b>KDLH</b>			Duluth Intl,
		APCH	
		T09	19
<b>KDYS</b>			Abilene/Dyess AFB,
		APCH	
		T16-W	19
		T34-W	19
<b>KEGI</b>			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18	19
		T36	19
<b>KENV</b>			Wendover,
		APCH	
		R08	5
<b>KHTO</b>			East Hampton,
		APCH	
		R10-X	5
<b>KLSV</b>			Las Vegas/Nellis AFB,
		APCH	
		T21LX	19
<b>KMTC</b>			Mount Clemens/Selfridge ANGB,
		APCH	
		T01	19
		T19	19

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KMTN</b>			Baltimore/Martin State,
		APCH	
		T15	19
		V15	11
<b>KNDZ</b>			Milton/Whiting Fld NAS South,
		APCH	
		T32	19
<b>KPAM</b>			Panama City/Tyndall AFB,
		APCH	
		T14LZ	19
		T32RZ	19
<b>KVKX</b>			Friendly/Potomac Airfield,
		APCH	
		R06	5
<b>KVPS</b>			Valparaiso/Destin-Ft Walton Be,
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
<b>LFBD</b>			Bordeaux/Merignac,
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
<b>LHKE</b>			Kecskemet,
		APCH	
		N12	5
		N30	5
<b>LHPA</b>			Papa AB,
		APCH	
		N16	5
<b>LIMS</b>			Piacenza,
		SID	
		GEN6Q	22
		KALM6Q	22
<b>MHTG</b>			Tegucigalpa/Toncontin Intl,
		APCH	
		H20	13

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>MRLB</b>			Liberia/Daniel Oduber Quiros I,
	APCH	V07	2
<b>MSSS</b>			San Salvador/Ilopango Intl,
	APCH	V15	5
<b>N07</b>			Lincoln Park,
	APCH	R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor,
	APCH	R07	5
		R25	5
		V07	5
<b>N85</b>			Pittstown/Alexandria,
	APCH	D08	5
<b>NTAA</b>			Tahiti/Faa'a,
	SID	ARIT4E	5
		ARIT4W	5
<b>NTTE</b>			Tetiaroa,
	SID	TAVI1E	5
		TAVI1W	5
<b>NTTG</b>			Rangiroa,
	APCH	V27-X	5
<b>NZTK</b>			Takaka,
	APCH	R18-Y	5
<b>NZWB</b>			Woodbourne,
	STAR	NORTHV	27
		WESTV	27
<b>OEGT</b>			Guriat Domestic,
	APCH	V28	2

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>OERR</b>			Arar Domestic,
	APCH		
		V10	2
<b>OPLA</b>			Lahore/Allama Iqbal Intl,
	APCH		
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
<b>OPRK</b>			Rahim Yar Khan/Sheikh Zayed In,
	APCH		
		V01	3
<b>PARS</b>			Russian Mission,
	APCH		
		R36	5
<b>RKSM</b>			Seoul Domestic,
	APCH		
		I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SBFZ</b>			Fortaleza/Pinto Martins Intl,
	APCH		
		V31	2
<b>SBKP</b>			Campinas/Viracopos Intl,
	APCH		
		H15-Y	13
<b>SKUL</b>			Tulua/Heriberto Gil Martinez,
	APCH		
		V02	5
<b>UHHM</b>			Chegdomyn,
	APCH		
		H13	5
		H31	5
<b>UHPK</b>			Ust-Kamchatsk,
	STAR		
		DOMUD2	5

\*See Reason Code table on page R1



Type	Procedure	Reason*
<b>UIUU</b>		Ulan-Ude/Mukhino,
	APCH	
	I08-Y	5
	N08-Y	5
	N08-Z	5
	STAR	
	BULE5H	5
	OSTU5H	5
	RIDL5H	5
	TOLG5H	5
<b>UKHK</b>		Kremenchuk/Velyka Kokhnyivka,
	APCH	
	N36	5
<b>URML</b>		Makhachkala/Uytash,
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
	GUDE1E	5
	GUDE1G	5
<b>URRT</b>		Taganrog/Yuzhny,
	APCH	
	N10-X	5
	N28-X	5
<b>UWKD</b>		Kazan,
	APCH	
	V11-X	5
<b>UWSK</b>		Krasny Kut,
	SID	
	X003	5
	X070	5
	X107	5
	X130	5
	X156	5
	X267	5
	X312	5
	X351	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen,
		APCH	
		V21	2
<b>WAJI</b>			Sarmi/Mararena,
		APCH	
		H13	5
		H31	5
<b>WAKE</b>			Mappi/Bade,
		APCH	
		H02	5
		H20	5
<b>WASA</b>			Maybrat/Ayawasi,
		APCH	
		H09	5
		H27	5
<b>WASI</b>			Inanwatan,
		APCH	
		H08	5
		H26	5
<b>WAUM</b>			Merdey,
		APCH	
		H27	5
<b>WAYK</b>			Kokonao,
		APCH	
		H13	5
<b>WIRR</b>			Tangerang/Budiarto,
		APCH	
		V30	5
<b>ZYTX</b>			Shenyang/Taoxian,
		STAR	
		ANS02A	22
		TOS02A	22

\*See Reason Code table on page R1

## Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55