

## Exclusion List for GE NavDBs in Cycle 2110

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 2110. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall
	APCH	
	R08	5
	R26	5
<b>012</b>		Brazil Clay County
	APCH	
	R27	5
<b>12N</b>		Andover/Aeroflex-Andover
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>CYYT</b>		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
<b>EBBE</b>		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

\*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

---

**EBBL**

Kleine Brogel

SID		
	BL05A	22
	BL05B	22
	BL05D	22

---

**EBFS**

Florennes

SID		
	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

---

**EGHC**

Penzance/Lands End

APCH		
	H07	5
	H16	5
	H25	5
	H34	5

---

**EGHE**

St Mary's/Scilly Isles

APCH		
	N27	5
	N32	5

---

**EGJA**

St Annes/Alderney

APCH		
	N08	5
	N26	5

---

**EGYD**

Cranwell

SID		
	SID1B	5

---

**EHEH**

Eindhoven

SID		
	EH5	22

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENBL</b>			Forde/Bringeland
		APCH	
		J07	1
		J25	1
<b>ENBN</b>			Bronnoysund/Bronnoy
		APCH	
		J03	1
<b>ENBS</b>			Batsfjord
		APCH	
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
		APCH	
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
		APCH	
		J04	1
		J22	1
<b>ENHK</b>			Hasvik
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes
		APCH	
		J20	1
<b>ENMH</b>			Mehamn
		APCH	
		J17	1
		J35	1
<b>ENMS</b>			Mosjoen/Kjaerstad
		APCH	
		J33	1
<b>ENNM</b>			Namsos
		APCH	
		J07	1
		J25	1

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>ENRM</b>		Rorvik/Ryum
	APCH	
	J04	1
	J22	1
<b>ENRS</b>		Rost
	APCH	
	J02	1
	J20	1
<b>ENSH</b>		Svolvaer/Helle
	APCH	
	J01	1
<b>ENSK</b>		Stokmarknes/Skagen
	APCH	
	J08	1
<b>ENSS</b>		Vardo/Svartnes
	APCH	
	J15	1
	J33	1
<b>ENST</b>		Stokka/Sandnessjoen
	APCH	
	J02	1
	J20	1
<b>ENVD</b>		Vadso
	APCH	
	J07	1
	J25	1
<b>EPPR</b>		Pruszcz Gdanski
	APCH	
	N27-X	5
	N27-Y	5
	N27-Z	5
<b>ETNG</b>		Geilenkirchen
	SID	
	NG227	22
<b>EVLA</b>		Liepaja
	APCH	
	I24-Z	5
	V06-Z	5
	V24-Z	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
	SID		
		LEP1E	5
		LEP1G	5
<b>KENV</b>			Wendover
	APCH		
		R08	5
<b>KHTO</b>			East Hampton
	APCH		
		R10-X	5
<b>KMTN</b>			Baltimore/Martin State
	APCH		
		T15	31
		V15	31
<b>KVKX</b>			Friendly/Potomac Airfield
	APCH		
		R06	5
<b>LFBD</b>			Bordeaux/Merignac
	SID		
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
<b>LHKE</b>			Kecskemet
	APCH		
		N12	5
		N30	5
<b>LHPA</b>			Papa AB
	APCH		
		N16	5
<b>LIMS</b>			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
<b>MHTG</b>			Tegucigalpa/Toncontin Intl
	APCH		
		H20	13
<b>MPRA</b>			Contadora/Cnel. Raul Arias Esp
	APCH		
		R18	21

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>MRLB</b>			Liberia/Daniel Oduber Quiros I
	APCH	V07	2
<b>MSSS</b>			San Salvador/Ilopango Intl
	APCH	V15	5
<b>N07</b>			Lincoln Park
	APCH	R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor
	APCH	R07	5
		R25	5
		V07	5
<b>N85</b>			Pittstown/Alexandria
	APCH	D08	5
<b>NTAA</b>			Tahiti/Faa'a
	SID	ARIT4E	5
		ARIT4W	5
<b>NTTE</b>			Tetiaroa
	SID	TAVI1E	5
		TAVI1W	5
<b>NTTG</b>			Rangiroa
	APCH	V27-X	5
<b>NZTK</b>			Takaka
	APCH	R18-Y	5
<b>NZWB</b>			Woodbourne
	STAR	NORTHV	27
		WESTV	27
<b>OEGT</b>			Guriat Domestic
	APCH	V28	2

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>OERR</b>			Arar Domestic
	APCH	V10	2
<b>PARS</b>			Russian Mission
	APCH	R36	5
<b>RKSM</b>			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
<b>RKSO</b>			Songtan-Si/Osan AB
	APCH	H27L	13
<b>SKUL</b>			Tulua/Heriberto Gil Martinez
	APCH	V02	5
<b>UHHM</b>			Chegdomyn
	APCH	H13	5
		H31	5
<b>UHPK</b>			Ust-Kamchatsk
	STAR	DOMUD2	5
<b>UIUU</b>			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR	BULE5H	5
		OSTU5H	5
		RIDL5H	5
		TOLG5H	5
<b>UKHK</b>			Kremenchuk/Velyka Kokhnyvka
	APCH	N18	5
		N36	5

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>URML</b>		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
	GUDE1E	5
GUDE1G	5	
<b>URRT</b>		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
<b>UWKD</b>		Kazan
	APCH	
V11-X	5	
<b>UWSK</b>		Krasny Kut
	SID	
	X003	5
	X070	5
	X107	5
	X130	5
	X156	5
	X267	5
	X312	5
X351	5	
<b>VTBK</b>		Nakhon Pathom/Kamphaeng Saen
	APCH	
V21	2	
<b>WAJI</b>		Sarmi/Mararena
	APCH	
	H13	5
H31	5	
<b>WAKE</b>		Mappi/Bade
	APCH	
	H02	5
H20	5	

\*See Reason Code table on page R1



	Type	Procedure	Reason*
<b>WASA</b>			Maybrat/Ayawasi
		APCH	
		H09	5
		H27	5
<b>WASI</b>			Inanwatan
		APCH	
		H08	5
		H26	5
<b>WAUM</b>			Merdey
		APCH	
		H27	5
<b>WAYK</b>			Kokonao
		APCH	
		H13	5
<b>WIRR</b>			Tangerang/Budiarto
		APCH	
		V30	5
<b>ZYTX</b>			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

\*See Reason Code table on page R1

## Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
21	Circling approach not compatible with FMS requirements
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55