

## Exclusion List for HWL NavDBs in Cycle 2309

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2309. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
<b>06N</b>		Middletown/Randall
	APCH	
	R08	5
	R26	5
<b>012</b>		Brazil Clay County
	APCH	
	R27	5
<b>12N</b>		Andover/Aeroflex/Andover
	APCH	
	R03	5
<b>2W2</b>		Westminster/Clairview Airpark
	APCH	
	R14	5
<b>9A5</b>		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
<b>CYYT</b>		St Johns Intl
	APCH	
	R10-X	5
	R16-X	5
<b>EBBE</b>		Beauvechain
	APCH	
	I04LY	5
	I22RX	5
	I22RY	5
	L04LY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
T22RY	5	

\*See Reason Code table on page R1

**Type Procedure Reason\***

SID

BE04C 5

BE04D 5

BE22A 22

BE22B 22

BE22C 5

BE22D 5

---

**EBBL**

Kleine Brogel

APCH

T05R 5

T23L 5

SID

BL05A 22

BL05B 22

BL05D 22

---

**EBFS**

Florennes

SID

FS08A 22

FS08B 22

FS08C 22

FS26A 22

FS26B 22

FS26C 22

---

**EGHC**

Penzance/Land s End

APCH

H07 5

H16 5

H25 5

H34 5

---

**EGHE**

St Mary's/Scilly Isles

APCH

N27 5

N32 5

---

**EGJA**

St Annes/Alderney

APCH

N08 5

N26 5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>EGNH</b>			Blackpool
	APCH		
		N10	3
<b>EGNV</b>			Teesside International
	APCH		
		N23	3
<b>EGPO</b>			Stornoway
	APCH		
		L36	3
		N18	3
		N36	3
<b>EGTE</b>			Exeter
	APCH		
		N26	3
<b>EHEH</b>			Eindhoven
	SID		
		EH5	22
<b>ENBL</b>			Forde/Bringeland
	APCH		
		J07	1
		J25	1
<b>ENBN</b>			Bronnoysund/Bronnoy
	APCH		
		J03	1
<b>ENBS</b>			Batsfjord
	APCH		
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
	APCH		
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
	APCH		
		J04	1
		J22	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENHK</b>			Hasvik
		APCH	
		J11	1
		J29	1
<b>ENLK</b>			Leknes
		APCH	
		J20	1
<b>ENMH</b>			Mehamn
		APCH	
		J17	1
		J35	1
<b>ENNM</b>			Namsos
		APCH	
		J07	1
		J25	1
<b>ENRM</b>			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
<b>ENRS</b>			Rost
		APCH	
		J02	1
		J20	1
<b>ENSH</b>			Svolvaer/Helle
		APCH	
		J36	1
<b>ENSS</b>			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
<b>ENST</b>			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
<b>ENVD</b>			Vadso
		APCH	
		J07	1
		J25	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>EPPR</b>			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
<b>ETNG</b>			Geilenkirchen
		SID	
		NG227	22
<b>EVLA</b>			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
<b>HLLM</b>			Tripoli/Mitiga Intl
		APCH	
		D10	2
		D28	2
<b>KDLH</b>			Duluth Intl
		APCH	
		T09	19
<b>KDYS</b>			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T34-W	19
<b>KEGI</b>			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Z	19
		T36-Z	19
<b>KENV</b>			Wendover
		APCH	
		R08	5
<b>KLSV</b>			Las Vegas/Nellis AFB
		APCH	
		T21LX	19

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KMFR</b>			Medford/Rogue Valley Intl-Medf
		APCH	
		R32-Y	5
<b>KMTC</b>			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
<b>KMTN</b>			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
<b>KNDZ</b>			Milton/Whiting Fld NAS South
		APCH	
		T32	19
<b>KPAM</b>			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
<b>KVKX</b>			Friendly/Potomac Airfield
		APCH	
		R06	5
<b>KVPS</b>			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02-Z	19
		T12-Z	19
		T20-Z	19
		T30-Z	19
<b>LFBD</b>			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
<b>LHKE</b>			Kecskemet
		APCH	
		N12	5
		N30	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LHNY</b>			Nyiregyhaza
		APCH	
		H18-Z	5
		H36-Z	5
<b>LHPA</b>			Papa AB
		APCH	
		N16	5
<b>MHTG</b>			Tegucigalpa/Toncontin Intl
		APCH	
		H20	13
<b>MMAN</b>			Monterrey/Del Norte Intl
		APCH	
		D20-4	2
<b>MSSS</b>			San Salvador/Ilopango Intl
		APCH	
		V15	5
<b>N07</b>			Lincoln Park
		APCH	
		R01	5
		R19	5
<b>N40</b>			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
<b>N85</b>			Pittstown/Alexandria
		APCH	
		D08	5
<b>NTAA</b>			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
<b>NTTE</b>			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
<b>NTTG</b>			Rangiroa
		APCH	
		V27-X	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>NZTK</b>			Takaka
	APCH	R18-Y	5
<b>NZWB</b>			Woodbourne
	STAR	NORTHV	27
		WESTV	27
<b>OPLA</b>			Lahore/Allama Iqbal Intl
	APCH	V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
<b>OPRK</b>			Rahim Yar Khan/Sheikh Zayed In
	APCH	V01	3
<b>PACJ</b>			Crooked Creek
	APCH	R14	5
	SID	AJOFY1	5
<b>PARS</b>			Russian Mission
	APCH	R36	5
<b>RKSM</b>			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
<b>SKUL</b>			Tulua/Heriberto Gil Martinez
	APCH	V02	5
<b>UHHM</b>			Chegdomyn
	APCH	H13	5
		H31	5
<b>UHPK</b>			Ust-Kamchatsk
	STAR	DOMUD2	5

\*See Reason Code table on page R1



Type	Procedure	Reason*
<b>UIUU</b>		Ulan-Ude/Mukhino
	APCH	
	I08-Y	5
	N08-Y	5
	N08-Z	5
	STAR	
	BULE5H	5
	OSTU5H	5
	RIDL5H	5
	TOLG5H	5
<b>UKHK</b>		Kremenchuk/Velyka Kokhnyivka
	APCH	
	N36	5
<b>URML</b>		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
	GUDE1E	5
	GUDE1G	5
<b>URRT</b>		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
<b>UUYI</b>		Inta
	SID	
	BABE1A	5
	BABE1B	5
	INTA1A	5
	INTA1B	5
	PERA1A	5
	PERA1B	5
	ROLE1A	5
	ROLE1B	5
<b>UWKD</b>		Kazan
	APCH	
	V11-X	5

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>UWSK</b>			Krasny Kut
		SID	
		X003	5
		X070	5
		X107	5
		X130	5
		X156	5
	X351	5	
<b>VTBK</b>			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
<b>WAJI</b>			Sarmi/Mararena
		APCH	
		H13	5
		H31	5
<b>WAKE</b>			Mappi/Bade
		APCH	
		H02	5
		H20	5
<b>WASA</b>			Maybrat/Ayawasi
		APCH	
		H09	5
		H27	5
<b>WASI</b>			Inanwatan
		APCH	
		H08	5
		H26	5
<b>WAUM</b>			Merdey
		APCH	
		H27	5

\*See Reason Code table on page R1

## Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55