

## Navigation Database Addendum

### **CORRECTION to AIRAC 1903 – Issue 2**

**SUP 09/2019 effective 04<sup>th</sup> March 2019**

### **ENVA Trondheim Vaernes**

---

#### **Runway 09**

Construction works will be carried out from 17 MAR 19 (2300) until 31 MAY 19 (2359)

During construction works, a TEMPO RWY 09 Z configuration will be established. The database during this period does NOT reflect THR 09 Z coordinates.

The new THR coordinates should read N63 27 27.50 / E010 53 59.00 elevation 16.7ft instead of N63 27 27.55 / E010 53 29.32 elevation 17ft.

	TORA (m)	TODA(m)	ASDA(m)	LDA(m)
RW09	2134	2134	2494	2036
RW27	2286	2286	2286	2053

Procedures valid from 17 MAR 19 (2300) until 31 MAY 19 (2359):

L09-Z (LOC Z RWY 09) and R09-Z (RNAV GNSS Z RWY 09) are based on the TEMPO RWY 09 Z configuration, which is NOT reflected in the Database.

Procedures valid from 28 FEB 19 (0000) until 17 MAR 19 (2259) and from 01 JUN 19 until 19 JUN 19:

I09-Y, L09-Y (ILS Y or LOC Y RWY 09) and R09-Y (RNAV GNSS Y RWY 09) are based on the standard THR coded in the Database.

**The following procedures are suspended for the whole period: I09, L09 (ILS or LOC RWY 09), R09 (RNAV GNSS RWY 09).**

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
8<sup>th</sup> March 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)