

Flight Safety Alert

CORRECTION to AIRAC 1805 – Issue 2

AMDT ED 02/18 effective 1st February 2018

EDDT Berlin Tegel

APCH ILS/LOC 08L, transitions KL08L, LA08L and LE08L

Waypoint "DT605" N52-31.4 E012-55.1 (N52-31-23.01 E012-55-03.42) should read "**DT552**" **N52-31.4 E012-55.1 (N52-31-22.79 E012-55-05.84)**.

Navdata will be updated effective AIRAC cycle 1806.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
13th April 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com