

Navigation Database Addendum

CORRECTION to AIRAC 1906 – Issue 2
NOTAM P3310/19 effective 16th May 2019

ETHL Laupheim

Runway RWY 27

NavDB does not reflect temporary displaced threshold 27 with the following coordinates: N48-13-11.94 / E009-54-50.10.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
21st May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com