

Navigation Database Addendum

AIRAC 1812 – Correction to Issue 8

NOTAM A0123/18 effective 8th November 2018

HSPN Port Sudan

SID: SINTA1B, ENADI1B, DEDES1B, UMERU1B, PUTAM1B, TUMAT1B
APCH: ILS RWY34, VOR/DME RWY34, VOR/DME RWY16, NDB RWY34, NDB RWY16,
RNAV GNSS RWY16, RNAV GNSS RWY34

Due to late reception of Notam A0123/18 the following procedures are not available in the database:

- SINTA1B
- ENADI1B
- DEDES1B
- UMERU1B
- PUTAM1B
- TUMAT1B
- ILS RWY34
- VOR/DME RWY34
- VOR/DME RWY16
- NDB RWY34
- NDB RWY16
- RNAV GNSS RWY16
- RNAV GNSS RWY34

In database existing procedures are not valid until 31December2018

Navdata will be updated effective AIRAC cycle 1813.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 9th November 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com