
Flight Safety Alert

AIRAC 1805 – Issue 6

AIRAC AMDT RP 061/16 effective 2nd February 2017

RPLL Manila Ninoy Aquino Intl

APCH ILS/LOC RWY 06

- MISAP should read "**Track 061deg. At 1000 ft, turn right to intercept radial 145 MIA VOR/DME. At 4000 ft turn right for holding at MIA VOR/DME or as instructed by ATC.**" instead of "Climb on RWY HDG to 5NM MIA VOR/DME, turn right HDG 125deg to intercept and track-out radial 095 MIA VOR/DME until reaching 4000ft, turn right direct to MIA VOR/DME and hold or as instructed by ATC."

Navdata will be updated effective AIRAC cycle 1807.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
14th May 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com