

---

## Flight Safety Alert

### **AIRAC 1805 – Issue 7**

**AIRAC AMDT RP 061/16 effective 2nd February 2017**

### **RPLL Manila Ninoy Aquino Intl**

---

#### **APCH VOR Y RWY 06**

- MISAP should read "**Climb to 1000ft, then right climbing turn to radial 145 MIA VOR/DME. Return to MIA VOR/DME at 4000ft or as instructed by ATC.**" instead of "Climb direct to MIA VOR/DME, track-out radial 062 to 5NM MIA VOR/DME, turn right HDG 125deg to intercept and track-out radial 095 MIA VOR/DME until reaching 4000ft, turn right direct to MIA VOR/DME and hold or as instructed by ATC."

Navdata will be updated effective AIRAC cycle 1807.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
16<sup>th</sup> May 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)