

---

## Flight Safety Alert

### **AIRAC 1805 – Issue 1**

**SG AIP effective 24<sup>th</sup> September 2015**

### **SGCO Concepcion / Teniente Coronel Carmelo Peralta**

---

#### **APCH NDB 03**

- Missed Approach turn direction to NDB “CON” (Concepcion) should read **LEFT** instead of RIGHT.

Navdata will be updated effective AIRAC cycle 1806.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
12<sup>th</sup> April 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)