

## Flight Safety Alert

### **AIRAC 1806 – Issue 6**

**AIP WMKI AD2.7-2 effective 9th November 2017**

### **WMKI Ipoh Sultan Azlan Shah**

---

#### **Waypoint OBMIN coordinates STAR IKILO A, NITIS A, SOTRO A, TUVSI A**

Waypoint OBMIN coordinates should read :

**N04-35.9 (N04-35-55.26) E100-53.4 (E100-53-23.17)** instead of  
N04-35.9 (N04-35-55.26) E101-53.4 (E101-53-23.17).

STARs : IKILO A, NITIS A, SOTRO A and TUVSI A should read :

**..-ADBAD-(131 DEG/15.3NM)-OBMIN-(185 DEG/8.2NM)-RIMGO-** instead of  
..-ADBAD-(200DEG/17NM)-OBMIN-(98 DEG/59.7NM)-RIMGO-.

Navdata will be updated effective AIRAC cycle 1807.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
25<sup>th</sup> May 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)