

---

## Flight Safety Alert

### **AIRAC 1806 – Issue 7**

**AIP AD 2 OICI SID 1-1 effective 23rd August 2012**

### **OICI Ilam**

---

#### **SID MOKAB 1K**

- Departure turn to VOR ILM (Ilam) should read **LEFT** instead of RIGHT.

Navdata will be updated effective AIRAC cycle 1808.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
07<sup>th</sup> June 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)