
Flight Safety Alert

AIRAC 1807 – Issue 1

AIP AD 2 OICI SID 1-1 effective 23rd August 2012

OICI Ilam

SID MOKAB 1K

- Departure turn to VOR ILM (Ilam) should read **LEFT** instead of RIGHT.

Navdata will be updated effective AIRAC cycle 1808.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
07th June 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com