
Flight Safety Alert

AIRAC 1808 – Issue 2

other USTP SE-3 effective 21st June 2018

KDAB Daytona Beach Intl

Holding SMYRA, APCH ILS or LOC RWY 25R

Missed approach holding at SMYRA, turn direction should read **LEFT** instead of RIGHT.

Navdata will be updated effective AIRAC cycle 1809.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 11th. July 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com