

## Flight Safety Alert

### AIRAC 1808 – Issue 3

### RJGG Nagoya/Chubu Centrair Intl

---

#### Holding POKER

- Turn direction for holding POKER should read "**Left**" instead of "Right". Length should read **5.6NM** instead of 5.0NM

Navdata will be updated effective AIRAC cycle 1809.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
18<sup>th</sup> July 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)