
Flight Safety Alert

AIRAC 1811 – Issue 1

SB SUP N214-A120/18 effective 11th Oktober 2018

SBFL Hercilio Luz Intl

APCH R32-W

- Do not use VNAV guidance on approach R32-W

Depending on the type of FMC, the vertical profile might lead to the not-displaced threshold RWY 32.

Navdata will be updated effective AIRAC cycle 1812.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
27th September 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com