
Flight Safety Alert

AIRAC 1902 – Issue 6

AIRAC AMDT 1/17 effective 5th January 2017

EGPK Prestwick

- **APCH LOC DME RWY 12**
- **APCH NDB DME RWY 12**

Missed approach holding turn direction should read **LEFT** instead of RIGHT.

Navdata will be updated effective AIRAC cycle 1903.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
1st February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com