

Flight Safety Alert

AIRAC 1902 – Issue 7

NFDD 007/2019 effective 28th February 2019

KAPC Napa County

APCH ILS or LOC RWY 36L, RNAV (GPS) Y RWY36L, RNAV (GPS) Z RWY36L RWY 36L THR coordinates

RWY 36L threshold coordinates should read **N38-12.5 W122-17.1 (N38-12-28.72 W122-17-06.98)** instead of N38-12.8 W122-17.0 (N38-12-45.21 W122-16-59.06).

Vertical profiles of ILS or LOC RWY 36L, RNAV (GPS) Y RWY36L and RNAV (GPS) Z RWY36L are coded to wrong threshold coordinates. Do not use VNAV guidance.

RWY 18R/36L length should read 5930ft instead of 4146ft.

Navdata will be updated effective AIRAC cycle 1903.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
6th Februar 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com