
Flight Safety Alert

AIRAC 1906 – Issue 9

AIP AD 2 ENRM 5-5 effective 2nd February 2017

ENRM Rorvik Ryum

APCH VOR 04

Missed approach point should read radial 218 RVK VOR, distance 1.1 NM RVK DME iso runway 04.

Missed approach procedure should read: climb direct to RVK VOR, continue on radial 039 RVK VOR, at 4.3 NM RVK DME right turn direct to RVK VOR, join RVK VOR holding climbing to 3000.

RVK holding: 038, right turn, 1 minute, minimum holding altitude 3000.

Navdata will be updated effective AIRAC cycle 1907.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
27th May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com