
Flight Safety Alert

AIRAC 1909 – Issue 4

SUP SL A07/ 2018 effective 21st June 2018

SLLP La Paz El Alto Intl.

APCH RNAV (GNSS) Z RWY 10 Missed approach

MISAP leg LP626 - LP627 should read: Track 182deg to LP627 instead of direct to LP627.

Navdata will be updated effective AIRAC cycle 1911.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
4th of September 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com