
Flight Safety Alert

AIRAC 1910 – Issue 2

KZMP Minneapolis ARTCC K3 United States

AWY Q92

AWY Q92 after MAASI should read
...HANKU - (087deg/ 76NM) - JORDY instead of
...HANKU - (078deg/512NM) - JORDI
Other details remain the same.

HWL systems are NOT affected by this error.

Navdata will be updated effective AIRAC cycle 1911.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
30th August 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com