

---

## Flight Safety Alert

### **AIRAC 2012 – Issue 2**

**NOTAM B2542/20 NOTAMR B2541/20 effective 21th September 2020**

### **RPVM Lapu Lapu Mactan-Cebu Intl**

---

#### **APCH VOR Y RWY 22**

Due to displacement of threshold runway 22:

Approach angle should read **2.64°** instead of 2.87° and altitude at MAPt should read **126ft.**

Disregard waypoint EP22.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 4<sup>th</sup> November 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)