

Navigation Database Addendum

AIRAC 1806 – Issue 7

AIRAC AMDT OP 01/18 effective 29th March 2018

OPPS Peshawar Bacha Khan Intl

APCH ILS and LOC Y RWY35 / ILS and LOC Z RWY35

- Localizer ident should read **IBKB** instead of IKBK.
Waypoint positions are correct.

Navdata will be updated effective AIRAC cycle 1807.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
23rd May 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com