
Navigation Database Addendum

AIRAC 1807 – Issue 6

NOTAM A2817/18, A2819/18, A2820/18, A2821/18 effective 21th June 2018

LPPR Francisco Sa Carneiro

ILS/LOC RWY 17, VOR RWY 17, VOR RWY 35

Due to late reception of document, the above mentioned approaches are not updated.

Navdata will be updated effective AIRAC cycle 1808.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
20th June 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com