

## Navigation Database Addendum

### **AIRAC 1810 – Issue 4**

**NOTAM A3342/18 NOTAM C A2841/18 effective 29th August 2018**

### **OIFM Shahid Beheshti**

---

#### **Runway 26L threshold coordinates**

Due to expiration of NOTAM A2841/18, RWY 26L threshold is no longer displaced.

- Threshold coordinates should read **N32-45.2 E051-53.1** (N32-45-10.68 E051-53-05.05)  
instead of **N32-45.1 E051-52.9** (N32-45-08.26 E051-52-51.55)

No change for VOR 26L and NDB 26L approaches.

Navdata will be updated effective AIRAC cycle 1811.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
30th August 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)