

Navigation Database Addendum

AIRAC 1903 – Issue 3

NOTAM P1101/19, P1102/19, P1103/19 effective 8th February 2019

ETHB Buckeburg

Runway 08 displacement

Coordinates of temporary displaced RWY 08 should read N52 16 42 E009 04 55 instead of N52 16 37.10 E009 04 17.07.

	TORA (m)	TODA (m)	ASDA (m)	LDA (m)
RW08	920	920	920	920
RW26	920	920	920	920

The database does NOT reflect displaced THR 08 coordinates.

Vertical profile of RNAV (GPS) RWY08 is coded to the original threshold coordinates.
Do not use VNAV guidance.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
11th February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com