

Navigation Database Addendum

AIRAC 1903 – Issue 14

NOTAM B0954/19 effective 19th February 2019

WIMN Raja Sisingamangaraja XII

APCH VOR 09, RNP 09;Runway RW09

Due to late resceiption of Notam mentioned above, THR coordinates for RW09 should read **N02 15.6 E098 58.7** (N02 15 36.22 E098 58 40.37) instead of **N02 15.6 E098 58.5** (N02 15 36.84 E098 58 27.56).

APP angle for RNP 09 should read 3.00° instead of 3.09°.

APP angle for VOR 09 should read 2.90° instead of 3.00°, ALT at MAPt SLG21 should read 5262ft instead of 5212ft.

Do not use VNAV guidance for both approaches.

Navdata will be updated effective AIRAC cycle 1904.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
26th February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com