
Navigation Database Addendum

AIRAC 1905 – Issue 2

SUP 13/19 effective 25th April 2019

ZSOF Hefei Luogang

SID BIPIM 12D, IKUBA 12D, MADUK 12D, MIDOX 12D, OREVO 12D

BIPIM 12D

Routing should read:

“- 334° to R334/D9.6 XQH - **284°** to PEDNU” instead of “-334° R334/D9.6 XQH - 292° to PEDNU”

IKUBA 12D, MADUK 12D, MIDOX 12D, OREVO 12D

Routing should read:

“- 334° to MNM 980ft - LT 244° - **intercept R157 HFC** to R157/D20.4 HFC” instead of “-334° to MNM 980ft - LT 244° - 154° HFC to R157/D20.4 HFC”

Navdata will be updated effective AIRAC cycle 1906.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
10th April 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com