

## Navigation Database Addendum

### **AIRAC 1906 – Issue 13**

**NOTAM A1538/19 effective 23<sup>rd</sup> May 2019**

### **VVCR Khanh Hoa / Cam Ranh Intl**

---

#### **several procedures**

SUP A07/19 postponed to 20 JUN 2019 by NOTAM A1538/19.

-----  
A1538/19 NOTAMN

Q)VVTS/QFATT/IV/BO/A/000/999/1200N10913E005

A) VVCR

B) 1906200000 C) 1907032359

E) TRIGGER NOTAM - AIRAC AIP SUP A07/19 DATED 23 MAY 2019 ADJUSTMENT OF CURRENT RWY PARAMETERS, OPERATION OF NEW RWY AND FLIGHT PROCEDURE CHARTS AT CAM RANH INTERNATIONAL AIRPORT: WILL BE VALID FM 0000 UTC ON 20 JUN 2019.

#### **RWY 02L/20R should read RWY 02/20.**

Following procedures in database shall not be used until 20 JUN 19: V20LY (VOR Y RWY 20L), V20RX (VOR X RWY 20R), H02LY (RNP Y RWY 02L), H20RY (RNP Y RWY 20R), I02LY (ILS Y RWY 02L), I02LX (ILS X RWY 02L), I02RY (ILS Y RWY 02R), I20LZ (ILS Z RWY 20L).

Following procedures are not in database: V20X (VOR Y RWY 20), V20W (VOR W RWY 20), I02Y (ILS Y RWY 02).

Navdata will be updated effective AIRAC cycle 1907.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
22<sup>nd</sup> May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)