
Navigation Database Addendum

AIRAC 1909 – Issue 2

NOTAM A1948/18 and A1951 DR effective 8th December 2018

DRZR Zinder

Runway RW05/ RW23

RWY 05 THR coordinates should read "**N13-46-26.44 E008-58-37.33**" instead of N13-46-26.60 E008-58-37.43

RWY 23 THR coordinates should read "**N13-47-07.86 E008-59-32.98**" instead of N13-47-02.30 E008-59-25.45

Do not use VNAV guidance on approach RNP RWY23.

Navdata will be updated effective AIRAC cycle 1910.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
6th August 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com