

---

## Navigation Database Addendum

### **AIRAC 1910 – Issue 1**

**SUP 18/19 effective 12th September 2019**

**NOTAM A4897/19 effective 12th September 2019**

### **UHMM Magadan Sokol**

---

#### **STAR RIMAL 5K**

#### **Waypoint MM039**

- Coordinates of **MM039** should read **N59-55-17.70 E151-36-21.90 (N59-55.3 E151-36.4)**  
instead of N59-55-17.70 E151-30-21.90 (N59-55.3 E151-30.4)
- Track / distance RIMAL-MM039-MM012 should read **262° / 21.1NM - 261° / 5.6NM**  
instead of 265° / 24NM - 242° / 3NM

Remark for NOTAM A4897/19: Coordinates MM026 correct in database

Navdata will be updated effective AIRAC cycle 1911.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
28<sup>th</sup> August 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)